


Item H2:

**Port of Anchorage Intermodal Expansion Project
North Extension/Wet Barge Berth Sheet Pile Inspections**



Wet Barge Berth and North Extension
Preliminary Inspection Summary Report
Volume 2 of 2

10 December 2010

Port of Anchorage Intermodal Expansion Project
North Extension/Wet Barge Berth Sheet Pile Inspections

Table of Contents

Sheet Pile Inspection Summary – 2010

Dive Inspections

Daily Dive Reports

Cell by Cell Findings


Post Dredging Subsidence

Subsurface Rocks

Sheet Pile Inspection Summary – 2010



LEGEND:
----- CELLS NOT INSTALLED
----- EXISTING CELLS
----- SHEETS REMOVED IN 2010



NOTE:
1. DATA REFLECTS INSPECTION FINDINGS OF SHEETS INSTALLED PRIOR TO THE 2010 SEASON, AND PULLED & INSPECTED DURING THE 2010 CONSTRUCTION SEASON (THROUGH 9/30/10). DATA DOES NOT REFLECT SHEETS INSTALLED DURING THE 2010 CONSTRUCTION SEASON.
2. PULLED SHEETPILE DATA AS OF 9/30/10.

NTS




421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com

Port of Anchorage Intermodal Expansion Project
2010 Sheetpile Inspection Summary
Project Overview

Sheet 1 of 4
12-9-10

- LEGEND:**
- CELLS NOT INSTALLED
 - EXISTING CELLS
 - NO MAJOR DAMAGE OBSERVED WHEN PULLED
 - DAMAGE OBSERVED WHEN PULLED
 - × FACE SHEET DAMAGE IDENTIFIED DURING DIVE INSPECTION



NOTES:

1. SYMBOLS ARE PLACED AT APPROXIMATE LOCATIONS OF SHEETS. REFER TO FIELD DOCUMENTATION & SHEETPILE RECORD FOR PRECISE DATA.
2. THE APPROXIMATED AREAS AND LOCATIONS IDENTIFIED IN THIS DRAWING REPRESENT PRELIMINARY FIELD DETERMINATIONS OF THE CONDITION OF THE EXTRACTED SHEETPILE.
3. ALL DEPTH ELEVATIONS ARE MEASURED IN FEET MEAN LOWER LOW WATER (MLLW).

NTS

4. PULLED SHEETPILE DATA AS OF 9/30/10.



421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com


Port of Anchorage Intermodal Expansion Project
2010 Sheetpile Inspection Summary
Wet Barge Berth (Cells 27-39)

Sheet 2 of 4

12-9-10

LEGEND:

- CELLS NOT INSTALLED
- EXISTING CELLS
- NO MAJOR DAMAGE OBSERVED WHEN PULLED
- DAMAGE OBSERVED WHEN PULLED
- × FACE SHEET DAMAGE IDENTIFIED DURING DIVE INSPECTION



NOTES:

1. SYMBOLS ARE PLACED AT APPROXIMATE LOCATIONS OF SHEETS. REFER TO FIELD DOCUMENTATION & SHEETPILE RECORD FOR PRECISE DATA.
2. THE APPROXIMATED AREAS AND LOCATIONS IDENTIFIED IN THIS DRAWING REPRESENT PRELIMINARY FIELD DETERMINATIONS OF THE CONDITION OF THE EXTRACTED SHEETPILE.
3. ALL DEPTH ELEVATIONS ARE MEASURED IN FEET MEAN LOWER LOW WATER (MLLW).

NTS

4. PULLED SHEETPILE DATA AS OF 9/30/10.



421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com


Port of Anchorage Intermodal Expansion Project
2010 Sheetpile Inspection Summary
North Extension (Cells 1-33)

Sheet 3 of 4

12-9-10

LEGEND:

- CELLS NOT INSTALLED
- EXISTING CELLS
- NO MAJOR DAMAGE OBSERVED WHEN PULLED
- DAMAGE OBSERVED WHEN PULLED
- × FACE SHEET DAMAGE IDENTIFIED DURING DIVE INSPECTION



NOTES:

1. SYMBOLS ARE PLACED AT APPROXIMATE LOCATIONS OF SHEETS. REFER TO FIELD DOCUMENTATION & SHEETPILE RECORD FOR PRECISE DATA.
2. THE APPROXIMATED AREAS AND LOCATIONS IDENTIFIED IN THIS DRAWING REPRESENT PRELIMINARY FIELD DETERMINATIONS OF THE CONDITION OF THE EXTRACTED SHEETPILE.
3. ALL DEPTH ELEVATIONS ARE MEASURED IN FEET MEAN LOWER LOW WATER (MLLW).

NTS

4. PULLED SHEETPILE DATA AS OF 9/30/10.



421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com

Port of Anchorage Intermodal Expansion Project
2010 Sheetpile Inspection Summary
North Extension (Cells 34-66)

Sheet 4 of 4


12-9-10

Dive Inspections

Sheet Pile Inspection Summary ~ 2010



LEGEND:
----- CELLS NOT INSTALLED
----- EXISTING CELLS
----- SHEETS REMOVED IN 2010



NOTE:

1. DATA REFLECTS INSPECTION FINDINGS OF SHEETS INSTALLED PRIOR TO THE 2010 SEASON, AND PULLED & INSPECTED DURING THE 2010 CONSTRUCTION SEASON (THROUGH 9/30/10). DATA DOES NOT REFLECT SHEETS INSTALLED DURING THE 2010 CONSTRUCTION SEASON.

NTS

2. PULLED SHEETPILE DATA AS OF 9/30/10.




421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com

Port of Anchorage Intermodal Expansion Project
2010 Sheetpile Inspection Summary
Project Overview

Sheet 1 of 4

12-9-10

- LEGEND:**
- CELLS NOT INSTALLED
 - _____ EXISTING CELLS
 - NO MAJOR DAMAGE OBSERVED WHEN PULLED
 - DAMAGE OBSERVED WHEN PULLED
 - ✕ FACE SHEET DAMAGE IDENTIFIED DURING DIVE INSPECTION



NOTES:

1. SYMBOLS ARE PLACED AT APPROXIMATE LOCATIONS OF SHEETS. REFER TO FIELD DOCUMENTATION & SHEETPILE RECORD FOR PRECISE DATA.
2. THE APPROXIMATED AREAS AND LOCATIONS IDENTIFIED IN THIS DRAWING REPRESENT PRELIMINARY FIELD DETERMINATIONS OF THE CONDITION OF THE EXTRACTED SHEETPILE.
3. ALL DEPTH ELEVATIONS ARE MEASURED IN FEET MEAN LOWER LOW WATER (MLLW).

4. PULLED SHEETPILE DATA AS OF 9/30/10.

NTS



421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com


Port of Anchorage Intermodal Expansion Project
2010 Sheetpile Inspection Summary
Wet Barge Berth (Cells 27-39)

Sheet 2 of 4

12-9-10

LEGEND:

- CELLS NOT INSTALLED
- EXISTING CELLS
- NO MAJOR DAMAGE OBSERVED WHEN PULLED
- DAMAGE OBSERVED WHEN PULLED
- × FACE SHEET DAMAGE IDENTIFIED DURING DIVE INSPECTION



NOTES:

1. SYMBOLS ARE PLACED AT APPROXIMATE LOCATIONS OF SHEETS. REFER TO FIELD DOCUMENTATION & SHEETPILE RECORD FOR PRECISE DATA.
2. THE APPROXIMATED AREAS AND LOCATIONS IDENTIFIED IN THIS DRAWING REPRESENT PRELIMINARY FIELD DETERMINATIONS OF THE CONDITION OF THE EXTRACTED SHEETPILE.
3. ALL DEPTH ELEVATIONS ARE MEASURED IN FEET MEAN LOWER LOW WATER (MLLW).

NTS

4. PULLED SHEETPILE DATA AS OF 9/30/10.



421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com


Port of Anchorage Intermodal Expansion Project
2010 Sheetpile Inspection Summary
North Extension (Cells 1-33)

Sheet 3 of 4

12-9-10

LEGEND:

- CELLS NOT INSTALLED
- _____ EXISTING CELLS
- NO MAJOR DAMAGE OBSERVED WHEN PULLED
- DAMAGE OBSERVED WHEN PULLED
- ✕ FACE SHEET DAMAGE IDENTIFIED DURING DIVE INSPECTION



NOTES:

1. SYMBOLS ARE PLACED AT APPROXIMATE LOCATIONS OF SHEETS. REFER TO FIELD DOCUMENTATION & SHEETPILE RECORD FOR PRECISE DATA.
2. THE APPROXIMATED AREAS AND LOCATIONS IDENTIFIED IN THIS DRAWING REPRESENT PRELIMINARY FIELD DETERMINATIONS OF THE CONDITION OF THE EXTRACTED SHEETPILE.
3. ALL DEPTH ELEVATIONS ARE MEASURED IN FEET MEAN LOWER LOW WATER (MLLW).

NTS

4. PULLED SHEETPILE DATA AS OF 9/30/10.



421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com

Port of Anchorage Intermodal Expansion Project
2010 Sheetpile Inspection Summary
North Extension (Cells 34-66)

Sheet 4 of 4

12-9-10

Dive Inspections

October 14, 2010

061028.3406D

Scott Yancey
Construction Group Manager
ICRC - Program & Project Management
421 West 1st Avenue, Suite 200
Anchorage, AK 99501


Subject: Port of Anchorage Expansion, Dive Inspection Report

Dear Mr. Yancey:

Please find enclosed the final Dive Inspection Report for the Port of Anchorage Expansion Wet Barge Berth (WBB) and North Extension (NE) sheet pile bulkhead face. You will find a graphical representation of the inspection effort and a narrative of the recorded findings. The field work effort was completed by PND Engineers and Global Offshore Divers with assistance from West Construction Company. Work was completed in October 2009 and July-Aug 2010.

INSPECTION RESULTS

The attached documents provide the findings of dive inspections completed to date. The term "damage" in this report generally refers to partially separated interlocks beginning at the bottom (tip) of the sheet and extending some distance up the sheet. Once an interlock has become separated, secondary damage can easily occur as the unsupported portions of sheets buckle, twist or bend. The length of the interlock separation (how far it extends up the sheet) is the most significant factor.



Examples of separated interlocks – WBB Cell 36 (left), face sheets pulled from NE Cell 39 (right).

For this inspection the seabed in front of the bulkhead face was dredged to approximately 10 feet above tip elevation. Therefore the damage visible during the dive inspection was typically more than 10 feet above the sheet pile tip elevation unless over-dredging increased access or lost fill material through damaged face sheets reduced access.

Key observations are as follows:

1. At the Wet Barge Berth, damage is present in every cell at face sheets or wyes at WBB cells 27-38. WBB cells 36-38 were removed during August-September 2010 and also found to have tailwall sheet damage.
2. At the North Extension cells 13-30, no damaged face sheets were found. NE cells 9-12, 31 and 32 were removed during August-September 2010 and were found to have face and tailwall sheet damage.
3. At the North Extension cells 41-66, damage is present at multiple cells spread throughout the entire area. NE cells 38-40 were removed during August 2010 and also found to have face and tailwall damage.

If you have any questions or desire clarification, please contact us at any time.

Sincerely,
PND Engineers, Inc.

Jim Campbell
Jim Campbell, P.E.
Senior Engineer

Attachments

- Dive Inspection Report

Dive Inspection Report

Port of Anchorage Expansion Wet Barge Berth and North Extension Bulkhead Project

Prepared for:
ICRC
421 West First Avenue, Suite 200
Anchorage, AK 99501

Prepared by:
PND Engineers, Inc.
1506 W. 36th Ave.
Anchorage, AK 99503

October 2010



TABLE OF CONTENTS

Dive Inspection Summary	1
Figure 1- Dive Inspection Map	4
Table 1- Dive Inspection Result Summary	5

Appendices

Appendix A	PND Daily Reports
Appendix B	Global Offshore Divers Report, October 2009
Appendix C	Global Offshore Divers Interim Report, August 2010
Appendix D	Global Offshore Divers Final Report, September 2010

Dive Inspection Summary

A dive inspection consists of an underwater diver cleaning a section of the wye piles, sheet pile interlocks, and face sheet pile manually or with a pressure washer. The diver then performs tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as the diver can reach. A limited dive inspection was performed in October 2009 at the Port of Anchorage (POA) Expansion. The diver found sheet pile damage at the Wet Barge Berth (WBB) cells 36 and 38. This damage consisted of partially separated interlocks and damage to sheet pile tips (bent or twisted sheet pile tips). Visual and gauge inspections were performed on sheet piles pulled from NE tail wall "I" which West Construction (WCC) was contracted to remove as part of the North Extension Bulkhead (NEB) project.

Based on the results of the October 2009 inspection, PND suggested further inspection of installed sheet piles at locations where similar hard driving conditions were encountered or similar contractor driving methods were used. Several cells in the Wet Barge Berth and North Extension were selected for inspection based on field observation, inspection reports, and contractor pile driving submittals. All of the selected cells encountered hard impact driving conditions, long duration of installation, high rates of fresh heading sheet piles, and variances from design tip elevation. During vibratory or impact driving localized damage to pile tops occasionally occurs prior to reaching planned sheet pile tip elevation. The pile is "fresh headed" to provide a clean, straight profile for the driving hammer to be placed on and pile driving is resumed. All of these conditions were present at WBB cells 36-38. The cells selected for dive inspection were WBB 27-35, NE 13-15, NE 40-43, NE 48-50, and NE 59-62.

U.S. Army Corps of Engineers (USACE) harbor expansion dredging was completed July 22, 2010 to approximately -39 MLLW (Mean Lower Low Water) then contractor inspection dredging to approximately -45 MLLW was performed in pockets in front of cells NE 40-43, NE 48-50, and NE 59-62. Upon completion of the inspection dredging pockets sink holes began forming on July 22 and July 23 in cells NE 60 and NE 63 respectively indicating a loss of fill material from behind the bulkhead. Dredge spoils were immediately returned to the outside of cells NE 59-63 prevent any further loss of material. Dredge spoils were also replaced outside of cells NE 48-50, even though no loss of fill was observed from those cells. Subsequent harbor expansion dredging exposed damaged sheet piles that led to fill loss from the following cells: WBB 27, WBB 33, WBB 34, NE 53, and NE 66.

PND Engineers, Inc. contracted Global Offshore Divers (Global) to perform inspection services. Global suggested use of sector scanning sonar to obtain preliminary images of the existing bulkhead to identify specific areas of interest, gross anomalies in the sheet pile bulkhead, and to assess diver safety and access at these locations. The sector scanning sonar was used to obtain images of cells NE 42-43, NE 48-52, and NE 59-64. The sonar images revealed a sheet (2nd to the south from the wye at 59/60) in cell 60 that was partially out of interlock and a spoils pile on the sea floor that appeared to originate from this location. After the site had stabilized, a diver was able to confirm the sheets were out of interlock beginning at approximately elevation -30 MLLW and provide video footage of the beginning of the separated interlocks. See attached Global dive reports and video.

Concurrently, West Construction was removing sheet pile from WBB 36-38, NE 9-11, NE 32 and NE 37-40 under the North Extension Bulkhead project. Many of the sheet piles being removed from these cells exhibited damage. Sheet pile damage generally consists of partially separated interlocks beginning at the bottom (tip) of the sheet and extending some distance up the sheet. Once an interlock has become separated, secondary damage can easily occur as the unsupported portions of sheets buckle, twist or bend. The length of the interlock separation (how far it extends up the sheet) is the most significant factor.



Examples of separated interlocks – WBB Cell 36 (left), face sheets pulled from NE Cell 39 (right).

Due to these findings, the dive inspection scope was expanded to include cells adjacent to WCC's planned work under the NEB project to ensure a competent place to begin building new sheet pile cells. The additional cells included NE 9-12, NE 28-32, and NE 41-43 (at a lower elevation than previously inspected). Damaged face sheet pile were identified by divers at NE 10-12 and at cell 40 by WCC while pulling previously installed sheets.

Based on the locations and extents of the damage being identified, the decision was made to dive inspect all existing NE cell faces, WBB cell faces 27-35, and continue monitoring tail wall sheet pile removal performed by WCC. Dive inspections were performed on WBB cells 27-35, NE 9-32, and NE 41-66 at varying depth due to concurrent dredging operations and material remaining against the face of the cells. A figure and summary table of the results of the dive inspection are attached.





Diagram illustrating the layout of the ship's hull and deck structure, showing numbered circles (27-35) and lettered hexagons (Z, AA, AB, AC, AD, AE, AF, AG, AH, AI) connected by dashed lines. A compass rose is located at the top right. The diagram is labeled "WET BARGE BERTH" and "TARGET INSPECTION DEPTH -28 MLLW".

The diagram shows a 29-column data table. The columns are labeled with letters: I, J, K, L, M, N, O, P, Q, R, S, T, U, V, W, X, Y, Z, AA, AB, AC, AD. The rows are numbered 9 through 29. A dashed line connects the top of column I to the bottom of column 10, and another dashed line connects the top of column J to the bottom of column 11. A vertical dashed line is also shown in column 12.

MATCHLINE

NORTH EXTENSION NORTH END
TARGET INSPECTION DEPTH -38 MLLW+/-



NTS

- MATERIAL LOSS FROM CELLS AFTER DREDGING
- ▲ WYE DAMAGE
- ⊖ FACE SHEET DAMAGE

1. NORTH EXTENSION AS-BUILT SHEET CELLS SHOWN FROM CONTRACTOR PROVIDED DECEMBER 9, 2009 SURVEY.
2. WET BARGE BERTH WYES BASED ON TWA SURVEY 8-10-2009.
3. DRY BARGE BERTH WYE LOCATIONS AND PARTIAL WET BARGE BERTH TAILWALLS FROM CONTRACTOR SUPPLIED "SHEET PILE AS-BUILT 2008" DXF FILE.
4. CELLS NOT SHOWN WERE NEVER CONSTRUCTED OR PULLED DUE TO KNOWN DAMAGE AS OF 9-20-2010.

MATCHLINE

NORTH EXTENSION SOUTH END
TARGET INSPECTION DEPTH -48 MLLW+/-

[illegible]

DATE:

1506 West 36th Avenue
Anchorage, Alaska 99503
Phone: 907.561.1011
Fax: 907.563.4220
www.pndengineers.com



PROJECT:		PORT OF ANCHORAGE EXPANSION PROJECT	
TITLE:		NORTH EXTENSION BULKHEAD PROJECT DIVE INSPECTION MAP	
DESIGNED BY:	KV	DATE:	10/13/10
CHECKED BY:	JC	PROJECT NO:	61026
		SHEET NO:	1 OF

TABLE 1. PORT OF ANCHORAGE NORTH EXTENSION BULKHEAD PROJECT - DIVE INSPECTION RESULTS

Inspection Date	Cell	Damage Type	Damage Location and Description	Estimated Elevation of Damage * (ft MLLW)	Estimated Mudline Elevation During Inspection * (feet MLLW)
9/11/2010	WBB 27	Split interlock and Fill lost from inside cell	Sheet 5-6 split interlock starts 12" off mud line. 4" gap at mud line. Fill lost from inside cell.	-18	-16 to -29 **
9/11/2010	WBB 27	Split interlock	Sheet 12 appeared buckled out seaward, Sheets covered in mud unable to determine extents of damage.	-16	-
9/13/2010	WBB 28	Split interlock at wye	Sheet 17 connection to 28/29 wye out of interlock 3 feet up from mud line. 3" gap at mud line. Sheet appeared pushed out to west side.	-14	-17 to -27 **
9/13/2010	WBB 29	Split interlock at wye	Sheet 17 connection to 29/30 wye out of interlock 12 feet up from mud line. 18" gap at mud line. Sheet appeared pushed out to the west side.	-16	-17 to -28 **
9/13/2010	WBB 30	Split interlock at wye	Sheet 17 connection to 30/31 wye out of interlock 2 feet up from mud line. 2" gap at mud line. Sheet appeared pushed in to the east side.	-16	-22 to -28 **
9/13/2010	WBB 31	Split interlock at wye	Sheet 17 connection to 31/32 wye out of interlock 4 feet up from mud line. 4" gap at mud line.	-10	-18 to -22 **
9/13/2010	WBB 32	N/A	WBB 32 not fully inspected due to thick mud stuck to face.	N/A	-18 to -27 **
9/2/2010	WBB 33	Split interlock at wye and Fill lost from inside cell	Sheet 1 connection to 32/33 wye out of interlock 14" up from mud line. 1.5" gap at mud line. Fill lost from inside cell.	-19	-20 to -25 **
9/2/2010	WBB 33	Split interlock	Sheet 11-12 starts 6 feet off mud line. 7" gap at mud line.	-19	-
9/2/2010	WBB 34	Split interlock at wye and Fill lost from inside cell	Sheet 1 connection to 33/34 wye out of interlock 5 feet up from mud line. 12" gap at mud line. Fill lost from inside cell.	-20	-25 to -26 **
9/2/2010	WBB 34	Split interlock	Sheet 3-4 starts 2.5 feet off mud line. 4" gap at mud line.	-23	-
9/2/2010	WBB 34	Split interlock	Sheet 9 bent out and south. Starts 2 feet off mud line. 3" gap at mud line.	-24	-
9/2/2010	WBB 34	Split interlock at wye	Sheet 17 connection to 34/35 wye out of interlock 10 feet up from mud line. 3-ft gap at mud line. Fill coming out of hole during inspection.	-15	-
9/2/2010	WBB 35	Bent sheets at wye	Sheets 1 and 2 were bent in toward the east. Wye damaged 10 feet up from mud line. Diver safety prevented further investigation.	-15	-26 **
10/22/2009	WBB 36	Split interlock(s)	Multiple damaged sheets found when cell was pulled by WCC during August 2010. See separate inspection records of pulled sheets.	-	-
10/22/2009	WBB 37	Split interlock(s)	Multiple damaged sheets found when cell was pulled by WCC during August 2010. See separate inspection records of pulled sheets.	-	-
10/22/2009	WBB 38	Split interlock(s)	Multiple damaged sheets found when cell was pulled by WCC during August 2010. See separate inspection records of pulled sheets.	-	-
8/16/2010	NE 9	N/A	All interlocks and wye connections intact to mud line.	N/A	-32 to -36 ***

TABLE 1. PORT OF ANCHORAGE NORTH EXTENSION BULKHEAD PROJECT - DIVE INSPECTION RESULTS

Inspection Date	Cell	Damage Type	Damage Location and Description	Estimated Elevation of Damage * (ft MLLW)	Estimated Mudline Elevation During Inspection * (feet MLLW)
8/16/2010	NE 10	Split interlock	Sheet 13-14 split interlock starts 4 feet off mud line. 1.5" gap at mud line.	-26	-30 to -36 ***
8/16/2010	NE 11	Bent sheets at wye	Sheet 1 is bent out 1.5 feet to the west side. Sheet appears wrinkled to 4 feet above mud line.	-26	-29 to -31 ***
8/16/2010	NE 11	Sheet out of both interlocks	The interlock between sheets 2 and 3 is ripped. Sheet 2 is bent out to the west side 6" and twisted.	-27	-
8/16/2010	NE 11	Horizontal rip in sheets	Sheets 11-14 ripped horizontally across the sheets and interlocks. Rip is approximately 3 feet above mud line. Center sheets are bent out to west side.	-27	-
8/16/2010	NE 11	Split interlock	Sheet 16-17 split interlock starts 3" below mud line.	-29	-
8/16/2010	NE 12	Sheet out of both interlocks	Sheet 1 appears bowed out to west side. Sheet 2 is out of both interlocks, bent 180 degrees and sticking up out of mud line 2 feet.	-26	-25 to -26 ***
8/19/2010	NE 13	N/A	All interlocks and wye connections intact to mud line.	N/A	-35 ***
8/19/2010	NE 14	N/A	All interlocks and wye connections intact to mud line.	N/A	-36 ***
8/19/2010	NE 15	N/A	All interlocks and wye connections intact to mud line.	N/A	-36 to -38 ***
8/19/2010	NE 16	N/A	All interlocks and wye connections intact to mud line.	N/A	-35 to -39 ***
8/19/2010	NE 17	N/A	All interlocks and wye connections intact to mud line.	N/A	-37 to -39 ***
8/19/2010	NE 18	N/A	All interlocks and wye connections intact to mud line.	N/A	-39 to -40 ***
8/19/2010	NE 19	N/A	All interlocks and wye connections intact to mud line.	N/A	-37 to -40 ***
8/19/2010	NE 20	N/A	All interlocks and wye connections intact to mud line.	N/A	-36 to -38 ***
8/19/2010	NE 21	N/A	All interlocks and wye connections intact to mud line.	N/A	-36 to -38 ***
8/20/2010	NE 22	N/A	All interlocks and wye connections intact to mud line.	N/A	-36 to -38 ***
8/20/2010	NE 23	N/A	All interlocks and wye connections intact to mud line.	N/A	-36 to -38 ***
8/20/2010	NE 24	N/A	All interlocks and wye connections intact to mud line.	N/A	-36 ***

TABLE 1. PORT OF ANCHORAGE NORTH EXTENSION BULKHEAD PROJECT - DIVE INSPECTION RESULTS

Inspection Date	Cell	Damage Type	Damage Location and Description	Estimated Elevation of Damage * (ft MLLW)	Estimated Mudline Elevation During Inspection * (feet MLLW)
8/20/2010	NE 25	N/A	All interlocks and wye connections intact to mud line.	N/A	-36 to -37 ***
8/20/2010	NE 26	N/A	All interlocks and wye connections intact to mud line.	N/A	-35 to -37 ***
8/18/2010	NE 27	N/A	All interlocks and wye connections intact to mud line.	N/A	-35 to -39 ***
8/18/2010	NE 28	N/A	All interlocks and wye connections intact to mud line.	N/A	-35 to -38 ***
8/18/2010	NE 29	N/A	All interlocks and wye connections intact to mud line.	N/A	-35 to -36 ***
8/18/2010	NE 30	N/A	All interlocks and wye connections intact to mud line.	N/A	-35 to -37 ***
8/18/2010	NE 31	N/A	All interlocks and wye connections intact to mud line.	N/A	-31 ***
8/18/2010	NE 32	N/A	All interlocks and wye connections intact to mud line.	N/A	-24 to -35 ***
9/13/2010	NE 41	N/A	All interlocks and wye connections intact to mud line.	N/A	-37 to -47 ***
9/13/2010	NE 42	N/A	All interlocks and wye connections intact to mud line.	N/A	-46 to -47 ***
7/28/2010	NE 43	N/A	All interlocks and wye connections intact to mud line.	N/A	-46 to -48 ***
9/7/2010	NE 44	N/A	All interlocks and wye connections intact to mud line.	N/A	-46 to -49 ***
9/7/2010	NE 45	N/A	All interlocks and wye connections intact to mud line.	N/A	-45 to -47 ***
9/7/2010	NE 46	N/A	All interlocks and wye connections intact to mud line.	N/A	-43 to -47 ***
9/7/2010	NE 47	Split interlock at wye	Sheet 1 connection to 46/47 wye out of interlock 2 feet up from mud line. 14" up from mud line sheet and wye bent in toward the east side. 12" gap at mudline	-38	-43 to -49 ***
9/7/2010	NE 48	N/A	All interlocks and wye connections intact to mud line.	N/A	-43 to -46 ***
9/7/2010	NE 49	N/A	All interlocks and wye connections intact to mud line.	N/A	-43 to -46 ***
9/7/2010	NE 50	Split interlock at wye	Sheet 1 connection to 49/50 wye out of interlock 6 feet up from mud line. 4" gap at mud line.	-40	-46 to -49 ***

TABLE 1. PORT OF ANCHORAGE NORTH EXTENSION BULKHEAD PROJECT - DIVE INSPECTION RESULTS

Inspection Date	Cell	Damage Type	Damage Location and Description	Estimated Elevation of Damage * (ft MLLW)	Estimated Mudline Elevation During Inspection * (feet MLLW)
9/7/2010	NE 50	Split interlock	Sheet 9-10 split interlock starts 18" off mud line. 8" gap at mud line.	-48	-
9/7/2010	NE 50	Bent sheet	Sheet 10 bent out at 5 feet above mud line. Sheet turns out to west side then back down into the mud 5 feet from the face of the cell.	-41	-
9/8/2010	NE 51	N/A	All interlocks and wye connections intact to mud line.	N/A	-44 to -48 ***
9/8/2010	NE 52	N/A	All interlocks and wye connections intact to mud line.	N/A	-44 to -51 ***
9/8/2010	NE 53	Split interlock at wye	Sheet 17 connection to 53/54 wye out of interlock 6 feet up from mud line. Sheet is buckled out from wye, ripped and bent. Fill lost from inside cell after dredging.	-34	-40 to -51 ***
9/8/2010	NE 54	N/A	All interlocks and wye connections intact to mud line. Spoils pile originating at cell 53 extends partially around cell 54. Sheet 1 may be deformed to East.	N/A	-40 to -45 ***
9/8/2010	NE 55	N/A	All interlocks and wye connections intact to mud line.	N/A	-44 to -46 ***
9/8/2010	NE 56	Split interlock at wye	Sheet 1 connection to 55/56 wye out of interlock 1 foot up from mud line. 8" gap at mud line. Sheet 1 is bent in toward the east side.	-43	-44 ***
9/8/2010	NE 57	N/A	All interlocks and wye connections intact to mud line.	N/A	-46 ***
9/8/2010	NE 58	N/A	All interlocks and wye connections intact to mud line.	N/A	-42 to -46 ***
9/9/2010	NE 59	N/A	All interlocks and wye connections intact to mud line. Spoils pile originating at cell 60 increased mud line elevation 8 feet from center of cell 59 to 59/60 wye.	N/A	-30 to -43 ***
7/31/2010	NE 60	Sheet out of both interlocks	Sheet 2 is out of both interlocks. The sheet is bent out to the west side for 15 feet then bends back toward the sea floor for 10 feet. Fill lost from inside cell.	-31	-30 to -40 ***
9/9/2010	NE 61	N/A	All interlocks and wye connections intact to mud line.	N/A	-42 to -46 ***
9/9/2010	NE 62	N/A	All interlocks and wye connections intact to mud line.	N/A	-45 to -48 ***
9/9/2010	NE 63	Fill lost from inside cell	Divers found all interlocks and wye joints intact to mud line. Fill lost from cell during dredging. Damage to sheets is likely below spoils pile from lost fill.	below -45	-45 to -47 ***
9/9/2010	NE 64	Split interlock	Sheet 13-14 split interlock starts 7 feet off mud line. 2.5" gap at mud line.	-40	-46 to -48 ***
9/9/2010	NE 65	N/A	All interlocks and wye connections intact to mud line.	N/A	-46 to -48 ***

TABLE 1. PORT OF ANCHORAGE NORTH EXTENSION BULKHEAD PROJECT - DIVE INSPECTION RESULTS

Inspection Date	Cell	Damage Type	Damage Location and Description	Estimated Elevation of Damage * (ft MLLW)	Estimated Mudline Elevation During Inspection * (feet MLLW)
9/9/2010	NE 66	Fill lost from inside cell	Divers found all interlocks and wye joints intact to mud line. Damage to sheets is likely below spoils pile from lost fill and south revetment fill sloughing after dredging. Mudline elevations increase as diver moved south along the face and then east around the cell.	below -40	-3 to -43 ***

TABLE NOTES:

- a. Inspection work was completed by Global Offshore Divers and PND Engineers, Inc. Cells WBB 27-35, NE 9-32 and NE 41-66 were inspected during Aug-Sept 2010. Cells WBB 36-38 were inspected during Oct 2009. Outfall cells, cells NE 1-8 and cells NE 33-40 have not been installed as of the inspection date. Cells NE 38-40 were partially installed but were not inspected and have since been removed. All inspected sheet piles were installed by QAP/MKB.
- b. This report does not include any results of tailwall inspections. Additional undiscovered damage may be present in tailwalls and face sheets beneath the mudline elevation at the time of the diver inspection. Generally, bulkhead face was dredged to within 10 feet of face sheet tip elevations prior to diver inspection. In some instances, sloughing, deposition or loss of fill through damaged face sheets resulted in partial in-filling of dredged areas before diver inspection was completed, resulting in reduced face sheet inspection depths.
- c. Diver inspection of cells WBB 36, 37 and 38 found damage at WBB cells 36 and 38. These three cells were removed during August 2010 by West Construction Company to implement repairs. Inspection of pulled sheets at that time found significant damage to face sheets in all three cells, and is documented in records from that work.
- d. Where damaged sheets are found it always involves split interlocks (sheets separated at the interlock) extending at least up to the mudline (10 feet +/- above tip of sheet), and associated bending or twisting of sheets.
- * Estimated elevations are based on a compilation of lead line soundings, pneumofathometer readings measuring water depth of the diver, and NOAA tide gauge readings for station 9455920 located at the Port of Anchorage. Elevations listed are for the highest extent of damage, and damage is assumed to extend below that elevation continuously to the sheet tip.
- ** Wet Barge Berth inspection depth varied significantly due to a 2 to 5-ft-thick wall of silt and clay that remained against the face of the sheets after dredging.
- *** The range of mudline elevations for cells NE 9-66 varied due to material being left behind after dredging in the areas approaching the wye piles.
- NE = North Extension
WBB = Wet Barge Berth
WCC = West Construction Company

Daily Dive Reports

APPENDIX A –PND DAILY REPORTS



ENGINEERS, INC. Copyright 2008

OCSP® Field Inspection Report Page 1 of 2

Project: POA North Extension- OCSP®		Date: 8-16-2010		Reviewed By	
PND Project No.: 061028		Day	Monday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Overcast	SHEET PILE CELL #’s	9-12
Project Manager	George Tipner	WIND	Light	TAIL WALL #’s	
Superintendant	Paul Johnson	TEMP	60 degrees F	TIME ON JOBSITE	(10hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:

Items Inspected/Locations/Comments

- Arrival on site 6:00 am. Low tide 7:05 am. Attended WCC Monday morning tool box safety talk.
- On site to coordinate Global Divers inspection of NE cell 9-12. Divers first entered the water at 10:38 am and worked from cell 12 North toward cell 9. Manson had dredged out the area in front of these cells to -35 to -40 MLLW. Some material remained piled against the wall causing the inspection depth to vary. For the purposes of this report face sheets inspected were numbered 1-17 from South to North.
- Cell 9 sheets were previously driven 10-15’ from grade. The assumed sheet pile tip elevations varied from -32 to -36’ MLLW based on survey provided by QAP in 2009. Due to the dredging on the outside of the cells some of the sheet tips were exposed. The 18 sheets that were at the face of the cell had all the interlocks checked from mud line to as high as the diver could reach (about 6’ up) all interlocks appeared to be intact and at least 5 of the sheets in the center of the cell were within about an inch of the mud line. In some cases the diver was able to feel the tips of the sheets and identify the picking holes.
- Cell 10 sheets were previously driven 10-15’ from grade. The assumed sheet pile tip elevations varied from -31 to -37’ MLLW based on survey provided by QAP in 2009. Due to the dredging outside the cell some of the sheet tips were exposed. On cell 10 the fifth sheet from the south wye (10/11) had one interlock (south) that was separated about 4’ above mud line and had about 1.5” gap between interlocks at the mud line. The north interlock of that sheet appeared different to the diver. He thought that the interlock may have been starting to separate but showed no gap to mud line. The remaining sheets were also high and the diver was able to see up to a foot of gap below the tips of these sheets and mud line. All tips and the remainder of the interlocks were ok.
- Cell 11 sheets were driven to 1 to 12 feet above grade. The assumed sheet pile tip elevations varied from -47 to -36’ MLLW based on survey provided by QAP in 2009. Multiple damaged sheets were located in this cell. The second sheet from the 11/12 wye had a separated interlock just below mud line that the diver could fit his gloved hand through. Sheets 5, 6, 7 were ripped and twisted away from the wall 3 feet up from mud line. Sheets 16 and 17 from (south to north) were also ripped and curled out like a corkscrew about 3 feet above mud line and small spoils pile formed outside the wall.
- Cell 12 sheets were assumed to be driven to grade with an estimated sheet tip elevation of -48 MLLW, no survey data was available for cell 12. Cell 12 had one sheet (#16) bent up and seaward for approximately 8 feet at the bottom. The diver initially noted the corner of a sheet sticking out of the mud but was unable to move it or uncover it. Another diver with a pressure washer was able to clear off some of the material covering the sheet and identify the 8’ length of sheet was bent out from the wall. Global Offshore Divers report to follow.
- Sheets pulled from cell 9 return wall were removed from Manson barge and placed on shore. One sheet showed a split interlock approximately 4’ from tip to the end of the sheets. The others sheets showed no major damage at the tip and varying degrees of damage due to pulling sheets with dredge bucket. See photos attached.



ENGINEERS, INC. Copyright 2008

OCSP® Field Inspection Report Page 2 of 2

PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

Photographs



Cell 9 return cell sheets after pulling.

Cells 9 sheet after pulling with dredge bucket.



Separated interlock at tip of sheets.

Separated interlock.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.




Project: POA North Extension- OCSP®		Date: 8-18-2010		Reviewed By	
PND Project No.: 061028		Day	Wednesday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Partly Cloudy	SHEET PILE CELL #s	27-32
Project Manager	George Tipner	WIND	Light	TAIL WALL #s	
Superintendant	Paul Johnson	TEMP	65 degrees F	TIME ON JOBSITE	(10hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:

Items Inspected/Locations/Comments


- Arrival on site 7:00 am. Low tide 9:10 am.
- On site to coordinate Global Divers inspection of NE cell 27-32. Divers first entered the water at 9:07 am and worked from cell 29 South toward cell 32. Divers performed tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as each diver could reach. Manson had dredged out the area in front of these cells to -35 to -40 MLLW. Some material remained piled against the wall causing the inspection depth to vary. Checked depths along accessible cells with the depth varying from approximately -35 MLLW at the wyes to -39 MLLW at the center of the cells. Approximate elevations based on weighted tape measurements and QAP supplied sheet pile top elevation surveys. Pneumofathometer readings from divers correlate to within 2 ft +/- . Verified depths on cells 27-30. Cell 31 and 32 were not accessible from the landside. For this report all diver comments are as heard over dive speaker. Diver report to follow.
- Cell 27-31: 17 face sheets interlocks and two wye pile connections in each cell were inspected by divers. The diver reported that all interlocks were intact and not deformed in the region inspected in all cells. Both wye piles were found to be intact and not deformed in the regions inspected in all cells.
- Cell 32 had a large pile of fill starting at the center of the cell and extending toward the south at roughly a 2 to 1 slope. This was the fill from the outfall B area spreading out and around the face of the cell. Based on pneumofathometer readings the sheets were inspected from approximately -35 to -24 MLLW starting at sheet 8 moving toward sheet 17 from North to South. 17 face sheets interlocks and one wye pile connections were inspected by divers. The diver reported that all interlocks were intact and not deformed in the region inspected.

PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

Photographs	
	
Divers setting up dive station in cell 28	Divers skiff working outside cell 29.
	
Manson Viking barge dredging to the North of cell 25.	

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.



Project: POA North Extension- OCSP®			Date: 8-19-2010		Reviewed By	
PND Project No.: 061028			Day	Thursday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Sunny		SHEET PILE CELL #’s	13-21
Project Manager	George Tipner	WIND	Light		TAIL WALL #’s	
Superintendant	Paul Johnson	TEMP	65 degrees F		TIME ON JOBSITE	(10hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:

Items Inspected/Locations/Comments

- Arrival on site 7:00 am. Low tide 10:43 am.
- On site to coordinate Global Divers inspection of NE cell 13-21. Divers first entered the water at 8:50 am and worked from cell 13-18 South with a pressure washer cleaning interlocks and face sheets down to mudline. Divers performed tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as each diver could reach. Manson had dredged out the area in front of these cells to -35 to -40 MLLW. Some material remained piled against the wall causing the inspection depth to vary. Checked depths along accessible cells with the depth varying from approximately -36 MLLW at the wyes to -39 MLLW at the center of the cells. Approximate elevations based on weighted tape measurements and QAP supplied sheet pile top elevation surveys. Pneumofathometer readings from divers correlate to within 2 ft +/- . Verified depths on cells 15-21. Cell 13 and 14 were not accessible from the landside. For this report all diver comments are as heard over dive speaker. Diver report to follow.
- Cell 13-21: 17 face sheets interlocks and two wye pile connections in each cell were pressure washed and inspected by divers. The diver reported that all interlocks were intact and not deformed in the region inspected in all cells. Both wye piles were found to be intact and not deformed in the regions inspected in all cells.
- Cell 22 had not been pressure washed and the 4th diver of the day was able to inspect the first 6 interlocks from the 21-22 wye. The diver’s clear water bag was punctured so no further interlocks were inspected. Cell 22-26 will be completed Friday 8-20-10.

PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.



Project: POA North Extension- OCSP®			Date: 8-20-2010		Reviewed By	
PND Project No.: 061028			Day	Friday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Sunny		SHEET PILE CELL #’s	22-26
Project Manager	George Tipner	WIND	Light		TAIL WALL #’s	
Superintendant	Paul Johnson	TEMP	65 degrees F		TIME ON JOBSITE	(6hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:

Items Inspected/Locations/Comments

- Arrival on site 7:00 am. Low tide 12:00 pm.
- On site to coordinate Global Divers inspection of NE cell 22-26. Divers first entered the water at 8:25 am and worked from cell 22-26 South with a pressure washer cleaning interlocks and face sheets down to mudline. Divers performed tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as each diver could reach. Manson had dredged out the area in front of these cells to -35 to -40 MLLW. Some material remained piled against the wall causing the inspection depth to vary. Checked depths along accessible cells with the depth varying from approximately -36 MLLW at the wyes to -38 MLLW at the center of the cells. Approximate elevations based on weighted tape measurements and QAP supplied sheet pile top elevation surveys. Pneumofathometer readings from divers correlate to within 2 ft +/- . Verified depths on cells 22-25. Cell 26 was not accessible from the landside. For this report all diver comments are as heard over dive speaker. 5 cells were completed today. Diver report to follow.
- Cell 22-26: 17 face sheets interlocks and two wye pile connections in each cell were pressure washed and inspected by divers. The diver reported that all interlocks were intact and not deformed in the region inspected in all cells. Both wye piles were found to be intact and not deformed in the regions inspected in all cells.
- WBB cells 27-35 are scheduled to be dredged over the weekend and will be dive inspected Monday and Tuesday (8/23-8/24).

PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.

Project: POA North Extension- OCSP®			Date: 9-2-2010		Reviewed By	
PND Project No.: 061028			Day	Thursday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Partly Cloudy		SHEET PILE CELL #’s	WBB 33-35
Project Manager	George Tipner	WIND	Light		TAIL WALL #’s	
Superintendent	Paul Johnson	TEMP	63 degrees F		TIME ON JOBSITE	(8hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:						
Items Inspected/Locations/Comments						
<ul style="list-style-type: none"> Arrival on site 7:00 am. Low tide 08:09. 						
<ul style="list-style-type: none"> For the purposes of this report all diver comments are as heard over dive speaker. All face sheets are numbered 1-17 from North to South. Sheet pile interlocks were found to be intact unless noted otherwise in this report. Diver report to follow. 						
<ul style="list-style-type: none"> On site to coordinate Global Divers inspection of WBB cell 27-35. It was reported that Manson had dredged out the area in front of WBB cells 27-35 to -25 to -30 MLLW. Preliminary depth measurements in Cells 27, 28, and 32 indicated material remaining against the sheet pile wall at elevations -6 to -8 MLLW. Depth measurements were taken on the inboard side of the dive skiff against the face of the sheets and outboard of the skiff approximately 7 feet off the face of the sheet pile in cells 33-35. These measurements indicated the material elevations at the face of cells 33-35 was approximately -25 to -26 MLLW with a small ledge then dropping off to approximately -28 to -30 MLLW roughly 7 feet off the wall. Pneumofathometer readings from divers correlate bottom elevations to within 2 ft +/- . Cells 33-35 were excavated to an unknown depth below the low tide line (approximately 0 MLLW) and had been seen flexing due to tidal in and out flow. This flexing may have led to the material on the outside of these cells being pushed and sloughed off. Some material loss from the inside of WBB cells 33 and 34 had been reported by ICRC and PND field reps. 						
<ul style="list-style-type: none"> Diver 1 first entered the water at 9:24 am at cell 32 and reported an 8 to 12 inch ledge at the face of the sheets that dropped off steeply for up to 20 feet (measured by pneumofathometer on the diver). Divers worked from cell 33-35 South with a pressure washer cleaning interlocks and face sheets down to mudline. Divers performed tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as each diver could reach. An underwater camera and clear water bag were used to shoot video footage of multiple interlock separations. Some areas were unable to be videotaped due to poor visibility or loose sediments sloughing out of the displaced joints. 						
<ul style="list-style-type: none"> WBB Cell 33: The first sheet that connects to the WBB cell 32/33 wye was observed to be out of interlock with the wye. The interlock was separated approximately 14 inches above mudline (approximately -20 MLLW). The gap between the interlock and wye was estimated to be 1.5 inches at mudline. The interlocks on Sheets 2-10 were reported to be intact to mudline. The interlock between sheets 11 and 12 was separated starting approximately 6 feet up from mudline (-25 MLLW) and the gap at mudline was estimated at 7 inches wide. The interlocks on Sheets 13-16 were reported to be intact to mudline. The interlock between sheet 17 and the 33/34 wye were separated starting approximately 5 feet above mudline (-25 MLLW). The gap at mudline was estimated to be 12 inches wide. 						

- WBB Cell 34: The first sheet was attached to the 33/34 wye. The interlock between sheets 1 and 2 had a 4” vertical crack in the knuckle approximately 3 feet above mudline (-25 MLLW). The interlock between sheets 3 and 4 were found to be separated 2.5 feet above mudline (-25 MLLW) with an estimated 4 inch gap at mudline. Sheet 9 was out of both interlocks approximately 2 feet above mudline with the sheet apparently bent out from the face tending to the South. Video images were taken of interlock separation. The interlock between sheets 11 and 12 was noted to be separated at mudline. No estimate of width or length was made. As the diver was cleaning sheets with the pressure washer he noted loose sediment sloughing and falling out of a large hole that originated at the 34/35 wye the diver began to retreat to the north to avoid this material.
- WBB Cell 35: The diver then surfaced to avoid the rubble pile and moved to the 35/36 wye and began cleaning and approaching the area from the south. The wye at cell 35/36 and sheets 3-17 were intact. The diver noted that sheets 1 and 2 were bent in toward the landside extending approximately 10 feet up from mudline (-25 MLLW). The gap was approximately 3 feet wide and the diver was able to reach through and feel loose sediment and rocks inside the cell. No further investigation of the area was performed due to diver safety concerns.
- WBB Cell 27-32: Due to the material remaining standing against the face sheets in this area no dive inspection was performed. Additional measures will be required to remove this material for further inspection.

PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.



Project: POA North Extension- OCSP®			Date: 9-7-2010		Reviewed By	
PND Project No.: 061028			Day	Tuesday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Overcast		SHEET PILE CELL #’s	NE 43-51
Project Manager	George Tipner	WIND	Light		TAIL WALL #’s	
Superintendant	Paul Johnson	TEMP	63 degrees F		TIME ON JOBSITE	(9hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:

Items Inspected/Locations/Comments

- Arrival on site 8:00 am. Low tide 13:48.
- For the purposes of this report all diver comments are as heard over dive speaker. All face sheets are numbered 1-17 from North to South. Sheet pile interlocks were found to be intact unless noted otherwise in this report. Diver report to follow.
- On site to coordinate Global Divers inspection of NE cell 43-51. It was reported that Manson had dredged out the area in front of NE cells 41-66 to -50 MLLW. Preliminary depth measurements in Cells 41-42 indicated material remaining against the sheet pile wall at elevations -18 to -26 MLLW. The granular fill from the open section of the bulkhead between NE Cells 32 and 40 was likely eroding and being transported into this area after dredging operations. Depth measurements were taken on the inboard side of the dive skiff against the face of the sheets in cells 40-50. These measurements indicated the material elevations at the face of cells 43-50 was approximately -45 to -49 MLLW with a small amount of material stacked against the face of the sheet wall and the areas approaching the wye piles being slightly higher. Pneumofathometer readings from divers correlate bottom elevations to within 2 ft +/- . Some material loss from the inside of NE cells 53 had been reported by ICRC and PND field reps and will be further investigated as soon as possible.
- Diver 1 first entered the water at 10:54 am at cell 43. Divers worked from cell 43-47 South with a pressure washer cleaning interlocks and face sheets down to mudline. Divers performed tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as each diver could reach. Divers continued inspections until currents became too strong for divers to hold the bottom. 4 Divers utilized today.
- NE Cells 43-45,48: All interlocks were found to be intact to mudline.
- NE Cell 46-47: The first sheet out of the wye in cell 47 was separated from the wye pile approximately 6’ above mudline (-43 MLLW). The gap between the sheets at mudline was estimated to be 12”. The wye and sheet were bent in toward shore at approximately 14” above mudline.
- NE Cell 49-50: the first sheet out of the wye in cell 50 separated from the wye pile approximately 6’ up from mudline (-46 MLLW). The gap between sheets at mudline was estimated at 4 inches. Sheets 9 and 10 were both bent out seaward from the face of the bulkhead. Sheet 9 to 10 interlock was split at 18” above mudline with an 8 inch gap. Sheet 9 bend slightly out from the face and penetrates below mudline. Sheet 10 is bent seaward with approximately 5’ of the sheet stick out flat to the bottom due west then the sheet is ripped, turns 90 degrees and penetrates below mudline.
- NE Cell 51: Sheet pile interlocks 1-8 and the sheet 1 to wye pile connections were found to be intact to mudline.



PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.

Project: POA North Extension- OCSP®		Date: 9-9-2010		Reviewed By	
PND Project No.: 061028		Day	Thursday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Overcast	SHEET PILE CELL #’s	NE 57-66
Project Manager	George Tipner	WIND	Light-Moderate	TAIL WALL #’s	
Superintendant	Paul Johnson	TEMP	60 degrees F	TIME ON JOBSITE	(6 hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:					
Items Inspected/Locations/Comments					
<ul style="list-style-type: none"> Arrival on site 10:00 am. Low tide 15:18. 					
<ul style="list-style-type: none"> For the purposes of this report all diver comments are as heard over dive speaker. All face sheets are numbed 1-17 from North to South. Sheet pile interlocks were found to be intact unless noted otherwise in this report. Diver report to follow. 					
<ul style="list-style-type: none"> On site to coordinate Global Divers inspection of NE cell 57-66 not including cell 60 which has had extensive damage identified within it. It was reported that Manson had dredged out the area in front of NE cells 41-66 to -50 MLLW. Depth measurements were taken from the land side at accessible points or from the dive skiff against the face of the sheets in cells 57-66. These measurements indicated the material elevations at the face of cells 57-66 was approximately -45 to -48 MLLW with a small amount of material stacked against the face of the sheet wall and the areas approaching the wye piles being slightly higher. Due to high tidal currents, depths in some areas were not able to be verified with lead line. Pneumofathometer readings from divers correlate bottom elevations to within 2 ft +/- . After dredging operations some material loss from the inside of NE cells 63 and 66 had been reported by ICRC and PND field reps. 					
<ul style="list-style-type: none"> Diver 1 first entered the water at 11:15 am at cell 57. Inspection began on cells 57-59 with nothing to report. Divers then worked from cell 66-61 North with a pressure washer cleaning interlocks and face sheets down to mud line. Divers performed tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as each diver could reach. 3 Divers utilized today. 					
<ul style="list-style-type: none"> NE Cells 57-59: All interlocks were found to be intact to mud line (-43 to -46 MLLW). As the diver approached the 59/60 wye he was steadily moving uphill on a spoils pile generated from known damage in cell 60. The spoils pile was approximately 8 feet high at the 59/60 wye. 					
<ul style="list-style-type: none"> NE Cell 61 and 62: All interlocks were found to be intact to mud line (-45 MLLW). 					

- NE Cell 63: Upon inspection diver noted approximately 3 feet of material built up as he approached the 62/63 wye. He used the pressure washer to clean the material below mud line (-42 MLLW) an additional 2 feet down and found all the interlocks to be intact. The fill loss previously noted was likely due to interlock damage located below the current mud line.
- NE Cell 64: Sheet pile interlocks 1-12 and the sheet 1 to wye pile connections were found to be intact to mud line. The interlock between sheets 13 and 14 was out of interlock approximately 6 feet up from mud line (-48 MLLW). The gap at mud line was approximately 2.5 inches.
- NE Cell 65: All interlocks were found to be intact to mud line (-48 MLLW).
- NE Cell 66: The elevation outside the cell beginning at the 65/66 wye was approximately -43 MLLW and steadily increased around the cell to -3 MLLW at sheet 39. This is likely due to material from the revetment at the south end of the project being undercut by dredging operations and rock and fill material raveling into the dredge cut. Divers inspected sheets 1 to 34 at mud line up as high as the diver could reach and found all interlocks intact. Two areas of interest were investigated further with the pressure washer used to push additional material from the base of the wall approximately 2 feet below mud line. No further damage was identified. The material loss was likely due to interlock damage located below the current mud line. Evidence of the rock and fill being undercut and raveling into the dredge trench was noted on the south side of cell 66.

PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.




Project: POA North Extension- OCSP®			Date: 9-9-2010		Reviewed By	
PND Project No.: 061028			Day	Thursday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Overcast		SHEET PILE CELL #’s	NE 57-66
Project Manager	George Tipner	WIND	Light-Moderate		TAIL WALL #’s	
Superintendant	Paul Johnson	TEMP	60 degrees F		TIME ON JOBSITE	(6 hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:

Items Inspected/Locations/Comments

- Arrival on site 10:00 am. Low tide 15:18.
- For the purposes of this report all diver comments are as heard over dive speaker. All face sheets are numbered 1-17 from North to South. Sheet pile interlocks were found to be intact unless noted otherwise in this report. Diver report to follow.
- On site to coordinate Global Divers inspection of NE cell 57-66 not including cell 60 which has had extensive damage identified within it. It was reported that Manson had dredged out the area in front of NE cells 41-66 to -50 MLLW. Depth measurements were taken from the land side at accessible points or from the dive skiff against the face of the sheets in cells 57-66. These measurements indicated the material elevations at the face of cells 57-66 was approximately -45 to -48 MLLW with a small amount of material stacked against the face of the sheet wall and the areas approaching the wye piles being slightly higher. Due to high tidal currents, depths in some areas were not able to be verified with lead line. Pneumofathometer readings from divers correlate bottom elevations to within 2 ft +/- . After dredging operations some material loss from the inside of NE cells 63 and 66 had been reported by ICRC and PND field reps.
- Diver 1 first entered the water at 11:15 am at cell 57. Inspection began on cells 57-59 with nothing to report. Divers then worked from cell 66-61 North with a pressure washer cleaning interlocks and face sheets down to mud line. Divers performed tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as each diver could reach. 3 Divers utilized today.
- NE Cells 57-59: All interlocks were found to be intact to mud line (-43 to -46 MLLW). As the diver approached the 59/60 wye he was steadily moving uphill on a spoils pile generated from known damage in cell 60. The spoils pile was approximately 8 feet high at the 59/60 wye.
- NE Cell 61 and 62: All interlocks were found to be intact to mud line (-45 MLLW).



- NE Cell 63: Upon inspection diver noted approximately 3 feet of material built up as he approached the 62/63 wye. He used the pressure washer to clean the material below mud line (-42 MLLW) an additional 2 feet down and found all the interlocks to be intact. The fill loss previously noted was likely due to interlock damage located below the current mud line.
- NE Cell 64: Sheet pile interlocks 1-12 and the sheet 1 to wye pile connections were found to be intact to mud line. The interlock between sheets 13 and 14 was out of interlock approximately 6 feet up from mud line (-48 MLLW). The gap at mud line was approximately 2.5 inches.
- NE Cell 65: All interlocks were found to be intact to mud line (-48 MLLW).
- NE Cell 66: The elevation outside the cell beginning at the 65/66 wye was approximately -43 MLLW and steadily increased around the cell to -3 MLLW at sheet 39. This is likely due to material from the revetment at the south end of the project being undercut by dredging operations and rock and fill material raveling into the dredge cut. Divers inspected sheets 1 to 34 at mud line up as high as the diver could reach and found all interlocks intact. Two areas of interest were investigated further with the pressure washer used to push additional material from the base of the wall approximately 2 feet below mud line. No further damage was identified. The material loss was likely due to interlock damage located below the current mud line. Evidence of the rock and fill being undercut and raveling into the dredge trench was noted on the south side of cell 66.

PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.



Project: POA North Extension- OCSP®		Date: 9-11-2010		Reviewed By	
PND Project No.: 061028		Day	Saturday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER		Sunny	SHEET PILE CELL WBB 27-32
Project Manager	George Tipner	WIND		Light-Moderate	TAIL WALL #'s
Superintendant	Paul Johnson	TEMP		60 degrees F	TIME ON JOBSITE (5 hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:

Items Inspected/Locations/Comments

- Arrival on site 10:00 am. Low tide 16:38.
- For the purposes of this report all diver comments are as heard over dive speaker. Sheet pile interlocks were found to be intact unless noted otherwise in this report. Diver report to follow.
- On site to coordinate Global Divers inspection of WBB cell 27-32. It was reported that Manson had dredged out the area in front of WBB cells 27-38 to -30 MLLW. Depth measurements were taken from the land side at accessible points or from the dive skiff against the face of the sheets in WBB cells 27-32. These measurements indicated the material elevations at the face of WBB cells 27-32 was approximately -10 to -30 MLLW with a large amount of material stacked against the face of the sheet wall and the areas approaching the wye piles being slightly higher. A large mud wall varying from 8" to 2 feet thick was stacked against the face of the sheets. WCC had been running a spud probe down the face sheets in an attempt to knock this wall of mud off. Their attempts appeared to have knocked 8 to 10 feet of the material off. This left the clear area available for inspection 10 to 20 feet above the target area (-30 MLLW). Pneumofathometer readings from divers correlate bottom elevations to within 2 ft +/-.
- Diver 1 first entered the water at 11:15 am at WBB cell 29. The diver noted a 2 foot ledge at the face of the cells which dropped off steeply toward the west. The mud wall at the face was approximately 10 feet high. The diver was instructed to move south and check if the face of WBB cells 30-32 were clean enough to inspect. The diver found the same mudwall present on all WBB cells checked (WBB 27-32). The mudwall varied in thickness from 8 inches to 2 feet and the top elevation varied from -22 MLLW to -10 MLLW at the north end near cells 27 and 28.
- WBB Cell 27: As the diver was working his way around the ledge on cell 27 he noted a vertical tear at the interlock between sheets 5 and 6 from the south wye. The interlock was separated approximately 12 inches above mudline with a gap of 4 inches at the mudline. The mudline was estimated to be -18 MLLW at the location of the damage. As the diver continued around the wall he noted sheet 12 protruding from the wall near the sheet 12 to 13 interlock. The interlock was separating at approximately -16 MLLW. The damaged area was covered in approximately 6 inches of dense packed clay and silt. The diver was not able to clear enough of the material off to determine the extents of the damage. Diver operations were suspended until more of the material is cleared from the face of the cells.
- I discussed with R. Marsh (ICRC) the need to remove more of the material from the face of the sheets prior to further dive inspection. He indicated that he would provide WCC direction to do so. I provided a sketch to ICRC of the areas of WBB cells 27-32 that needed additional clean up.



PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.




Project: POA North Extension- OCSP®		Date: 9-13-2010		Reviewed By	
PND Project No.: 061028		Day	Monday	Reviewed Date	
CONTRACTOR:	West Construction	WEATHER	Sunny	SHEET PILE CELL #’s	NE 41-42, WBB 28-32
Project Manager	George Tipner	WIND	Light	TAIL WALL #’s	
Superintendent	Paul Johnson	TEMP	60 degrees F	TIME ON JOBSITE	(7 hrs)

OBSERVED PROGRESS, UNUSUAL CONDITIONS, MEETINGS:

Items Inspected/Locations/Comments

- Arrival on site 13:00. Low tide 17:54.
- For the purposes of this report all diver comments are as heard over dive speaker. All face sheets are numbered 1-17 from North to South unless noted otherwise. Sheet pile interlocks were found to be intact unless noted otherwise in this report. Diver report to follow.
- On site to coordinate Global Divers inspection of NE cell 41-42 and WBB cells 28-32. It was reported that Manson had dredged out the area in front of NE cells 41-66 to -50 MLLW. Depth measurements were taken from the land side at accessible points or from the dive skiff against the face of the sheets in cells NE 41-42. These measurements indicated the material elevations at the face of cells 41-42 was approximately -37 to -47 MLLW with a small amount of material stacked against the face of the sheet wall and the areas approaching the wye piles being slightly higher. Pneumofathometer readings from divers correlate bottom elevations to within 2 ft +/-.
- NE Cell 41-42: Diver 1 first entered the water at 14:07 at cell 41. Divers then worked from cell 41 South with a pressure washer cleaning interlocks and face sheets down to mud line. Divers performed tactile and clear water bag visual inspections of all or a portion of the interlocks and wye pile connections from mud line to as high as each diver could reach. Inspection was conducted on cells 41-42 with nothing to report. 2 Divers utilized today.
- WBB Cells 28-32: Previous dive inspection at this location had indicated a mud wall from 8 inches to 2 feet thick at the top remaining against the face sheets after dredging to – 30 MLLW. WCC had been using a modified spud pile to remove the material from the face of the cells. Paul Johnson (West) indicated that the crew was almost complete with its latest effort to remove material from the face of the sheets to be inspected. The divers were relocated to the WBB area and entered the water to try to determine the effectiveness of the material removal operation. Lead line soundings and Pneumofathometer readings indicated that the elevation of the top of the ledge had been lowered considerably in some areas and little in others. Mudline elevations varied from approximately -16 MLLW to -29 MLLW. The decision was made to inspect cells at the current mudline elevations. The diver began cleaning interlocks with the pressure washer near mudline from the 27/28 wye working south. All sheets were cleaned and later inspected on cells 28, 29, and half of 30. At the midpoint of cell 30 the diver encountered a near vertical face of the mud wall remaining against the face of the cells extending up approximately 14 feet. The diver left the pressure washer behind, climbed up the face of the wall and began surveying the elevation and thickness of the top of the ledge. The diver was also performing a brief visual and tactile inspection of interlocks as he progressed south to cell 32/33 wye. Cells to the south of this location were previously inspected. Once the extents of the mud wall and ledge were surveyed the diver returned to cleaning interlocks near the top of the ledge. The diver reported that the ledge was unstable and he was able to push several partially separated chunks loose. The dive supervisor determined there was a risk of large chunks or portions of the wall falling onto the diver or his hoses. Cleaning operations on top of the ledge were stopped and the diver returned to the cleaned areas at the lower elevation and resumed inspection there.



- WBB Cell 28: Sheet 17 that enters the 28/29 wye interlock was separated to 3 feet above mudline (-17 MLLW). The sheet appeared pushed out to the west with approximately 3 inch gap at mudline.
- WBB Cell 29: Sheet 17 that enters the 29/30 wye interlock was separated to 12 feet above mudline (-28 MLLW). The sheet appeared pushed out to the west with approximately 3 inch gap at mudline.
- WBB Cell 30: Sheet 17 that enters the 30/31 wye interlock was separated to 2 feet above mudline (-20 MLLW). The sheet appeared pushed in to the east with approximately 2 inch gap at mudline.
- WBB Cell 31: Sheet 17 that enters the 31/32 wye interlock was separated to 4 feet above mudline (-18 MLLW). The sheet and wye had approximately 4 inch gap at mudline.
- WBB Cell 32: No damage was reported. The diver did not fully clean and inspect interlocks. The brief inspection that did occur was at elevations -18 MLLW at 31/32 wye and sloped down to -27MLLW at 32/33 wye.

PND is not responsible for Contractors safety programs, QC program, Contractors equipment, methods or procedures of operation.

BY Kai Vedenoja TITLE PND Staff Engineer

All work monitored was performed in accordance with the plans and specifications to the best of my knowledge, unless noted otherwise in this report.



On October 22 2009 Global Offshore Divers performed a subsea inspection for PN&D at the New Port of Anchorage which is currently under construction. This Inspection was performed on sheet pile cells WBB38, WBB37, WBB36. The areas inspected were the sheet pile interlocks about 2ft off the sea floor.

The New Port of Anchorage is located in the Cook Inlet basin. The water visibility in this area is zero. The inspection diver used two methods for inspecting the sheet pile interlocks. First he feels the interlock for uniformity to see if the thumb of the sheet pile was out of the joint. Then he would scrape out debris from the pile interlock using a thin knife blade. The next step is to utilize a clear water bag and an underwater light. The water bag is placed over the joint and the light is shown into the bag. Next the diver presses their face plate against the bag. The bag, light, and diver adjust till the diver can see the joint. This method can be difficult because dirty water can remain in the joint or there can be debris left that can make it difficult to see the joint. Also you are looking at a small area. For more thorough inspection, the area can be cleaned using a water blaster that provided a 20,000 psig water stream.

Cell WBB36 was also inspected from the north Y connection to the south Y connection point. At the North Y connection the sheet that connects to the Y was found out the joint. This sheet along with the next sheet to the south were curled in toward the center of the cell. The diver could reach in and touch the tail wall about 3 feet in to the cell. The two sheets were bent in a triangle shape inward. The sheet to the south of Y connection was also out of the interlock joint for about 3 ½ feet running upward. The bottom of the damage was at the mud line. The Y connection interlock was bent or ripped. At the third sheet over from the Y connection the sheet pile appeared to be normal. The balance of the interlocks to the south were also inspected (15 total not counting the two sheets south of the north Y connection) appear to be intact.

Cell WBB37 was inspected from the north Y connection to the south Y connection point. 18 interlocks were inspected. The fourth interlock from the south Y connection may be showing signs of the sheet coming out of the joint but the diver wasn't able to completely verify.

Cell WBB38 was inspected from the north Y connection to the tail wall in three feet of water. At the North Y connection the sheet that connects to the Y was found out the joint just above the mud line. It was out of the joint for about 3 ½ feet. The sheet was also pushed in about 2 inches and there was a horizontal rip in the sheet for about 6 inches. The area would look like a triangle with the bottom right corner pushed in. A total of 33 interlocks were inspected on this cell.

If additional inspections are required it is recommended that the inspections be completed using high pressure water to clean the joints along with vessel for dive support.

5400 Eielson St • Anchorage, Alaska 99518 • WWW.GDIVING.COM • 24hr Line: 907.563.9060 • Fax:
907.563.9061



APPENDIX C – GLOBAL OFFSHORE DIVERS INTERIM
REPORT, AUGUST 2010



Survey of Sheet Pile on North Extension of the Port of Anchorage – Preliminary Results

Anchorage, Alaska

WORK ORDER NUMBER:

30936

Performed For:

PND Engineers Inc.
1506 W 36th Ave
Anchorage, AK

5400 Eielson Street • Anchorage, AK 99518 • WWW.GDIVING.COM • 24 Hr: (907) 563-9060 • Fax:
(907) 563-9061



GLOBAL OFFSHORE DIVERS

Table of Contents

Survey of Sheet Pile on North Extension of the Port of Anchorage – Preliminary Results 1

 Anchorage, Alaska..... 1

Article I. EXECUTIVE SUMMARY 3

Article II. INTRODUCTION 4

Article III. 3.0 METHODOLOGY 4

 Section 3.01 PERSONNEL 4

 Section 3.02 Survey Techniques 5

Article IV. REPORT INVESTIGATION RESULTS 6

 Section 4.01 Cell 41 6

 Section 4.02 Cell 42 6

 Section 4.03 Cell 43 7

 Section 4.04 Cell 49 7

 Section 4.05 Cell 50 8

 Section 4.06 Cell 51 9

 Section 4.07 Cell 60 9

 Section 4.08 Cell 61 10

 Section 4.09 Cell 62 10

 Section 4.10 Cell 63 10

Article V. Attached Sonar Results 11

Article VI. Exhibit A 12

Article VII. Exhibit B 13

Article VIII. Exhibit C 14

Article IX. Exhibit D 15

Article X. Exhibit E 16

Article XI. Exhibit F 17

Article I. EXECUTIVE SUMMARY

Global Offshore Divers was requested by PND to survey the sheet pile comprising the retaining wall associated with the North Expansion of the Port of Anchorage.

The survey was accomplished using sector scanning sonar and divers.

The survey was done on July 28th – 31st.

This report compiles the information recovered during both the diver and sonar survey on cells 41-43, 49-51, and 60 – 63.

The areas surveyed had the area on the seaward side of them dredged to an elevation of -45’. A 12” to 24” column of seafloor material remained against the many of the cells above the dredged elevation.

No significant damage was found within any of the surveyed cells except for cell 60, where significant displacement and separation of the individual sheets exist.

The end of a piece of sheet pile was found in front of cell 50, roughly 18” from the wall.

Article II. INTRODUCTION

Global Offshore Divers was requested to investigate the condition of the individual sheets contained in certain cells on the North Expansion of the Port of Anchorage. Initial requests identified cells in the areas of cells 60, 42, and 50 to be surveyed.

Dredging operations on the seaward side of the sheet pile in this area and the resultant sloughing action witnessed from the land side of the sheets caused some concern over diver safety working under sheets with unknown structural integrity. This combined with the ambient in water conditions of no visibility and quick currents prompted Global to recommend using a sector scanning sonar to investigate the sheets prior to a diver survey. Both sonar and divers were used to obtain the results in this survey.

The following information was sought through the efforts of the survey:

- Sheet pile connectivity through the interlocks
- Deviations from plumb or straight as designed conditions
- Separation or gaps between the sheet pile
- Foreign debris or material located at the base of the sheet pile

Elevation information is not calculated in this report, as no datum or baseline was provided to Global at the time of the survey. Depth readings are given in this report along with times taken for elevations to be calculated.

In attendance of the survey at different times throughout the survey were:

Kai Vedenoja – PND Engineers, Inc.
Chris – ICRC
Terry - ICRC

Article III. 3.0 METHODOLOGY

Section 3.01 PERSONNEL

The survey was carried out under the direction of John Juettner for Global Offshore Divers.

J. Juettner	-Lead Diver
W. Posten	-Sonar Technician
J. Ferrier	-Diver
B. Daily	-Diver
J. Pool	-Diver
B. Rosenberger	-Diver
J. Zimmer	-Tender
D. DeVilbiss	-Report Compiler

The following equipment was utilized in the survey of the cells:

Surface Supplied Diving Station utilizing low pressure primary air supply with high pressure back up reserve.

Mesotech 1071 high resolution self calibrating Sector Scanning Sonar with MS 1000 software utilized with standoff bracket. See Exhibit A for details.

Deep Sea Power and Light SeaCam color video system with built in LED lights. See Exhibit B for details.

3-D direct drive pneumo fathometer gauge

Clear water bag

Section 3.02 Survey Techniques

An overall drawing of the cell locations were provided to Global Offshore Divers and included in this report as Exhibit C. Drawings indicative of each cell were provided to Global Diving by PND. Examples of these drawings are attached in Exhibit D. A different copy of the drawing was established to record the notes and data from each cell. These field notes are included in this report in Exhibit E. The numbering system used in this report follows the numbering system provided on the drawings, with the cells number sequentially from North to South, and the individual sheets in each cell numbered sequentially from North to South.

Earlier dredging activities at the locations under question had indicated the potential for unstable material below water line. After a review, it was determined that it would be safer to perform the diving work after a low tide while the hydrostatic pressure was increasing on the seaward side of the wall as opposed to increasing. In an effort to increase safety for the diver as well as obtain more data, it was also determined to utilize the sector scanning sonar in advance of the diving work.

The sonar survey was accomplished by placing the sonar head unit on a bracket that allowed the unit to be placed horizontally at a set distance out from the wall. The sonar head was placed at set elevations along the wall. Images were obtained at each location. Real time analysis was performed to be able to continue with diving activities. Following the sonar survey, the images were then collaged together to create an image of the wall as a whole on each of the sections. These images are included as a part of this report.

The dive inspection was performed according to the following procedure. The diver would leave surface above the area to be inspected, and travel to the toe of the bank where the mudline met the sheetpile. The diver would orient himself to identify which sheet he was on. The diver would then feel from mudline up as far as he could reach on each interlock of the individual sheets. Any discrepancies or anomalies would then be investigated and reported. The diver would periodically clean an area of joint and use a clear water bag to visually inspect the location. The diver would systematically move along the base of the sheet pile inspecting each sheet until the entire cell was surveyed at the lowest 6 feet available to the diver. Certain joints were not inspected due to material clingage on the sheets, and have been identified as un-surveyed in this report. Underwater video was taken on cell 60, showing the interlock between sheets 2 and 3. This video is included in this report as Exhibit F. Depths of water were obtained using a calibrated pneumofathometer gauge.

Article IV. REPORT INVESTIGATION RESULTS

Results of the survey are compiled in this section. They are broken out as follows:

- ▲ Cell 41
- ▲ Cell 42
- ▲ Cell 43
- ▲ Cell 49
- ▲ Cell 50
- ▲ Cell 51
- ▲ Cell 60
- ▲ Cell 61
- ▲ Cell 62
- ▲ Cell 63

Section 4.01 Cell 41

Survey Technique: Diver and Sonar
Water depth to mudline: 48’
Time at depth measurement: 1700, July 28th, 2010
Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. The joints between sheets 11 and 13 were difficult to clean due to mud and rock clingage. The joint between sheets 15 and 16 was not inspected due to rocks and mud clingage. The mudline against the wall was higher near the connecting joints to the adjacent cells, presumably due to the proximity of the clamshell to that portion of the wall during dredging.

Sonar results: See Attached Sonar Results

Section 4.02 Cell 42

Survey Technique: Diver and Sonar
Water depth to mudline: 48’
Time at depth measurement: 1715, July 28th, 2010

Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. Heavy buildup of rock material existed against the sheet pile wall. The mudline against the wall was higher near the connecting joints to the adjacent cells, presumably due to the proximity of the clamshell to that portion of the wall during dredging.

Sonar results: See Attached Sonar Results

Section 4.03 Cell 43

Survey Technique: Diver and Sonar
Water depth to mudline: 48’
Time at depth measurement: 1725, July 28th, 2010
Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. The northern sheets were found to be more free of mud clingage than the southern ones. A slight anomaly was found at the interlock between cell 43 and 44, and was later determined to be an extrusion mark from manufacturing. This anomaly can be seen above waterline at low tide.

Sonar results: See Attached Sonar Results

Section 4.04 Cell 49

Survey Technique: Diver and Sonar
Water depth to mudline: 61’
Time at depth measurement: 0830, July 31st, 2010
Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. A 12” ledge was observed at mudline against the sheet wall that dropped off into deeper water where the dredging had occurred. A crack like indication was visible on a field splice on the joint between cells 49 and 50, roughly 12’ below the top of the sheet pile. This crack like indication was observed by the crew in the skiff and was out of the water.

Sonar results: See Attached Sonar Results

Section 4.05 Cell 50

Survey Technique: Diver and Sonar

Water depth to mudline: 61'

Time at depth measurement: 0840, July 31st, 2010

Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. A 24" ledge was observed at mudline against the sheet wall that dropped off into deeper water where the dredging had occurred. At sheet 11, an end of a sheet pile was found sticking out of the bottom toward the vertical sheet 11 at a 45 degree angle in the manner indicated by the representative picture below. The end of the sheet was perpendicular to the vertical sheets on the wall and 18" inches away from the sheet pile wall. The diver was not able to move the sheet end, and was unable to determine the sheet's length or connectivity to the wall.



Representative model of sheet pile end found at sheet 11 in cell 50.

At the end of the dive in cell 50, the divers downline was found to be severely shredded and damaged roughly 20' below the surface of the water. This prompted a search for what may have caused the damage. The diver transited across the cell wall in 8' vertical increments from mudline to the surface of the water. No anomaly was found that could have caused this damage.

Sonar results: See attached Sonar Rusults

Section 4.06 Cell 51

Survey Technique: Diver and Sonar

Water depth to mudline: 61'

Time at depth measurement: 0850, July 31st, 2010

Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. An 18" ledge was observed at mudline against the sheet wall that dropped off into deeper water where the dredging had occurred.

Sonar results: See Attached Sonar Results

Section 4.07 Cell 60

Survey Technique: Diver and Sonar

Water depth to mudline: 63' outside of spoils pile

Time at depth measurement: 0945, July 31st, 2010

Diver results: The interlock connection between sheets 1-2 and 2-3 was found to be torn and separated at a water depth of 56' at 1002 on July 31st, 2010. Sheet 2 separates from the wall at that point and makes nearly a 165 degree bend toward the water's surface for 15', and then bends downward at a 45 degree angle towards the sea floor for 10'. The entire sheet is bent roughly 15 degrees to the North as well as having vertical displacement. The end of the pile is exposed in the water column. A spoils pile was observed spilling out from the back side of the cell at the location of the displaced sheet 2. Throughout the rest of the cell not covered by the spoils pile, a 12" ledge was observed against the sheet pile at mudline that drops off into deeper water. All interlocks inspected other than the ones between 1, 2 and 3 were found to be without damage. Sheet #1 and the connection joint to cell #59 were not inspected due to the unknown stability of the spoils pile and obstacle to the diver presented by the deformation of sheet #2. Sheet 3 appeared to be vertical and not displaced. Sheets 17 and 18 on cell 59 were inspected at this time and were found to be without damage.

Sonar results: See Attached Sonar Results

Section 4.08 Cell 61

Survey Technique: Diver and Sonar
Water depth to mudline: 60'
Time at depth measurement: 1320, July 31st, 2010
Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. An 18" ledge was observed at mudline against the sheet wall that dropped off into deeper water where the dredging had occurred.
Sonar results: See Attached Sonar Results


Section 4.09 Cell 62

Survey Technique: Diver and Sonar
Water depth to mudline: 60'
Time at depth measurement: 1340, July 31st, 2010
Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. An 18" ledge was observed at mudline against the sheet wall that dropped off into deeper water where the dredging had occurred.
Sonar results: See Attached Sonar Results

Section 4.10 Cell 63

Survey Technique: Diver and Sonar
Water depth to mudline: 65'
Time at depth measurement: 1110
Diver results: All interlocks on the sheets were found to be without damage as well as the connecting joints to each adjacent cell. An 18" ledge was observed at mudline against the sheet wall that dropped off into deeper water where the dredging had occurred.
Sonar results: See Attached Sonar Results

Submitted Without Prejudice,
David DeVilbiss
Alaska Regional Manager,
Global Offshore Divers



Article V. Attached Sonar Results


Sonar Image Results

Descriptions of distortions types labeled on sonar images are as follows:
(Applies to all Images)

- 1. Smearing is due to shape of sheet pile wall
- 2. False targets are due to back side radiation
- 3. Reflections always goes through the sonar origin
- 4. Slant range distortion makes strait targets look bent near the origin
- 5. Random Bend is distortion due to sonar base movement in strong current wash.
- 6. Surface reflection causes multipath distortion (ghost images).


Dim 58-64 Point of interest

- 1. 30m Range
 - a. View 58 through 64 point of interest is at south side of cell 59 with spill pile damage centered a north side of cell 60.
 - b. Horizontal dimensions indicate approximate distance in low point in trenched area. Vertical dimensions indicate approximate distance from bottom of trench to top of point of interest.




1, 2 Dim 58-64 Point of interest

- 2. 30m Range
 - a. Approximate height of mud line before dredging. Note height of point of interest, marked sheet pile, compared to height of mud line.



3 Dim 59-61 Point of interest I

- 3. 20m Range
 - a. Approximate height mud line before dredging and height of Point of interest above trench bottom. Add- top mud line, slab height, surface reflection and distortion.








Interlocks on sheets appear to be straight and without gaps. The joints between 11 and 16 are visible on the sonar image.




Interlocks on sheets appear to be straight and without gaps. Note: the mud line was higher to the left of cell 42, as described by the diver.



Interlocks on sheets appear to be straight and without gaps. Cell 44 is visible to the right of cell 43 in the sonar image.




Interlocks on sheets appear to be straight and without gaps. The circled images along the mud line indicate an anomaly near the location that the divers discovered 18" from the pile walls and approximate location of sheet 11.




Interlocks on sheets appear to be straight and without gaps.





Interlocks on sheets appear to be straight and without gaps.




The parturitions shown on the sonar images from the south side of cell 59 are leaving long shadows angling down and to the left. This indicates that the anomalies are standing off the cell wall with approximately the same width as the sheet pile. Observe that the interlocks run continues from the top of the anomaly and come out aligned at the bottom of the anomaly's shadow. This could suggest that the interlocks on cell 59 are continues.




Note: The center of the spill pile is on the north side of cell 60 and is below the protruding anomaly indicating an opening in the cell wall at the intersection of cell 59 and 60. All other cell interlocks on the sheets appear to be straight and without gaps to the right of the top of the spill pile.



Interlocks on sheets appear to be straight and without gaps.



Interlocks on sheets appear to be straight and without gaps.



Interlocks on sheets appear to be straight and without gaps.



Article VI. Exhibit A

MS 1000 Scanning Sonar



Kongsberg Mesotech Ltd. is the recognized world leader in mechanically scanned sonar systems. The MS 1000 Scanning Sonar Processor confirms our reputation as the supplier of the highest quality, highest resolution products in the market.


Our MS 1000 software program converts any standard PC into a full-function sonar processor *without the need for additional boards or hardware*, and is designed under ISO standards to ensure compliance to reliability, statutory and regulatory requirements.

MS 1000 is a Windows-based application and can be configured to control the complete digital line of Kongsberg Mesotech's scanning sonar, altimeter, and bathy sensor products via industry-standard telemetry protocols.




MS 1000 key features include:


- Simultaneous multiple scanning sonar head and altimeter operation, and sensor configurations
- Time-tagged recording of all sonar and sensor inputs to the PC's hard-drive or external recording device
- Advanced target measurement and annotation tools
- Track Plotter module allowing the user to pre-plot search and survey lines, and to geo-reference sonar targets
- Networking capability
- Target tracking (optional)



- Ping synchronization for multiple-head operation; fused data display for dual head profiling
- GeoTiff image format
- 3D profiling with pan device
- Plug-and-play USB keypad



Oil rig, pipeline, and diver



WWII shipwreck at 40m



Bridge foundation

Image courtesy Faguo Chance, Inc.

Image courtesy Tuukitiede off Commercial Diving, Estonia


Courtesy Fensomaker & Associates Inc.

Technical Specifications

- Minimum System Requirements 1 GHz, Pentium 3, 512 MB of RAM (single head operation), Windows 2000 Pro, Windows XP Pro, or Windows Vista Business Edition
- Video Format Platform dependent; SXGA (1280x1024 or higher recommended)
- Image Dedicated image area for each sonar head; size/position configurable
- Palette Menu selectable
- Sonar Control Pull-down menus for configuring and control of sonar system
- Status Readout Alphanumeric display of cursor positions, range, gain, mode settings
- Sensor Readout Alphanumeric display of position data, sensor outputs
- Gain Menu adjustable; infinite settings
- Range Menu adjustable; customer-defined; 5-500 meters
- Sector Width Adjustable from 7.2° to 360° in 7.2° steps
- Sector Center Adjustable from 0-360° in 0.9° steps
- Cursors Selectable by pointing device; 2 general purpose
- Zoom x2, x4
- Magnifier x1 to x10
- Menu Controls Menu driven control system for display mode, scan speed, scan reverse, threshold, speed of sound, serial I/O, profile or image selection, baud rate selection

- Data Recording and Playback Imaging, profile and time-tagged sensor data storage to hard drive or other PC device; bitmap snapshots to disk; GeoTiff format support
- Measurement Tools Detailed annotation, cursors, tape measure, target area, target height
- Printer Output to any printer recognized by operating system
- Telemetry RS 232, RS 485, RS 422
- Telemetry Rates Down link: 9600
Uplink selectable: 9600, 19K, 38K, 57K, 115K bit/s, 230K, 460K with USB interface box
- Power Requirement Platform dependent
- Temperature Range Platform dependent
- Navigation Input NMEA 0183 Format (232 Levels)
- Sensor Interface RS232

Typical System Configuration



KONGSBERG MESOTECH LTD.
1598 Kebet Way, Port Coquitlam, BC Canada V3C 5M5
Tel: (604) 464-8144 Fax: (604) 941-5423
Website: www.kongsberg-mesotech.com
E-mail: km.sales.vancouver@kongsberg.com



Article VII. Exhibit B



SS-1370C

INTEGRATED COLOR
VIDEO/LIGHTING SYSTEM
EXTREMELY DURABLE
ULTRA BRIGHT
LED LIGHTS
CRISP, WIDE-ANGLE
IMAGE



The SS-1370C color video camera is the newest addition to DeepSea's rugged video inspection series. Packed into a housing 1.37 in. (3.48 cm) in diameter is a 1/3" format color CCD and powerful lighting system. The SS-1370C is designed to withstand the rigors of day-to-day inspection in areas where environmental and mechanical shock are expected and unavoidable.

Features that contribute to SS-1370C durability and reliability include a stainless steel housing and a sapphire crystal lens port (where the camera looks through). The precipitation hardened housing, will resist wear in contact with tough materials, such as cast iron, and the lens port is virtually scratchproof except to diamond or carbide. Thirty-five ultra bright white LEDs protected by a smooth, chip and crack resistant window provide powerful, virtually indestructible lighting for the life of the camera. The 1/3" lens is fixed-focus, meaning there are no moving parts to break loose or wear. Each SS-1370C is pressure-tested and guaranteed to 100 meters (330 ft.) underwater.

The SS-1370C has applications in pipe inspection, borehole inspection, water wells, fixed-mount monitoring (such as observing underwater valves), tank and void inspection, and security and safety monitoring in water-based entertainment and architectural installations. It is suitable wherever a compact camera with built-in lighting is the best solution.

SS-1370C Combined Video & Lighting System

Specifications		Electrical	
Video		Power	8 to 13.2 volts DC
Image Sensor	1/3" CCD image sensor	Current	130 mA (camera), ~460 mA with LEDs at full illumination
Number of Pixels	510 (H) x 492 (V) (NTSC)	Connector	BHSS3MP
Resolution (TV lines)	330 (H) x 480 (V)	Pin-Out	1 = Ground, 2 = +12 VDC, 3 = Video Signal
Lens	2 mm, f3.5	Environmental	
Focus	Fixed focus, factory set	Operating Temperature	-10 C to 50 C (14 F to 122 F)
Minimum Focus	1/2-inch	Depth Rating	100 meters (330 ft.)
Scene Illumination	0.5 lux	Weight air/water	88 g/62 g (3.1 oz/2.1 oz)
Field of View in Air	111 (H) x 95 (V) x 122 (D) deg.	Mechanical	
Field of View in Water	76 (H) x 67 (V) x 82 (D) deg.	Camera Diameter	3.48 cm (1.37 in)
Lighting	45 white LEDs with variable intensity	Camera Length	5.46 cm (2.15 in), excluding collar (included)
Video Output	1.0 volt, peak-to-peak, at 75 ohm	Housing Materials	Sapphire crystal lens port. Impact-resistant LED window. Stainless Steel housing.
Video Format	Color; NTSC or PAL		
Shutter	Electronic, automatic		

Cables			
Camera Connector	Cable Type	Length	Dry-End Termination
740-055-004: Also available as un-terminated whip.	RG-59 Triax (TRI): 75 ohm video cable with polyethylene jacket.	0-1000 feet: Price is per-foot. Contact DeepSea for pricing.	TOP/SS: Standard. Also available on unterminated 18" whip.
	Kevlar Triax (KTRI): 75 ohm video cable with internal Kevlar braid and polyurethane jacket.		Other: Please contact DeepSea with requirements.
How to Order:	740-055-004) - (

Power & Viewing	
SST-1370 heads are ideally suited to work as a system with our family of controllers, which include the ability to vary the LED light intensity, view the image with high resolution monitors, output the video signal to other monitors and VCRs, or make video recordings with Hands-Free audio overlay.	
Power+	(P+) 120 vac/60 Hz (or 220 vac/50 Hz) to ~12 vdc power supply. Includes direct connection for SS3ILMP terminated cables. RCA video output interfaces with customer-supplied monitors and VCRs. Variable LED intensity controller allows fine adjustment of lighting for different conditions. A Ground Fault Circuit Interrupt (GFCI) is included on the AC cord for added safety.
Monitor+	(M+) A P+ with high-resolution surveillance monitor (>850 TV lines) enclosed in a rugged, aluminum case. A metal sunshade folds down to protect the CRT screen and front panel controls during transport. A tilt-stand improves viewing angle when system is on the ground. Includes direct connection for TOP/SS-terminated cables. Variable LED intensity controller allows fine adjustment of lighting for different conditions. Video in/out jacks allow hook up to external devices such as VCRs, camcorders and other remote monitors. A Ground Fault Circuit Interrupt (GFCI) is included on the AC cord for added safety.
Monitor+VCR	(M+VCR) (Release pending) An M+ with added VHS VCR and Hands-Free audio recording. Video/audio out jacks, CB mike input jacks, front-panel wireless microphone and playback speaker, one-button monitor/record/play.



Specifications subject to change without notice


DEEPSEA POWER & LIGHT • 3855 Ruffin Rd. • San Diego, CA 92123 USA • TEL (858) 576-1261 • FAX (858) 576-0219

web: <http://www.deepsea.com> • e-mail: info@deepsea.com


Rev. 9/21/00

WBB 27

EXISTING



PLAN



75'

61 2 3 4

67 8 9 10

Sheet length

Sheet # in series

Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA

DATE PULLED (LAST UPDATE 9/1)

●

Face/Tailwall Matchpoint

Damage identified by ICRC QA

Damage observed and recorded by Vest

△


Sheet pile found out of interlock, per ICRC QA observations

Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING

NTS




PLAN




EXISTING

NTS





PLAN





LEGEND

75' → Sheet length
6 1 2 3 4 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)
8/3 - RV
→ ICRC QA
→ DATE PULLED (LAST UPDATE 9/1)

● Face/Tailwall Matchpoint


 Damage identified by ICRC QA
 Damage observed and recorded by West

 Sheet pile found out of interlock, per ICRC QA observations
 Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING

NTS



PLAN



LEGEND

75' → Sheet length
6 1 2 3 4 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)
8/3 - RV
→ ICRC QA
→ DATE PULLED (LAST UPDATE 9/1)


● Face/Tailwall Matchpoint

Damage identified by ICRC QA
Damage observed and recorded by West


Sheet pile found out of interlock, per ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING



PLAN



75'

6

1

2

3

4

5

6

7

8

9

10

Sheet length

Sheet # in series

Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA

DATE PULLED (LAST UPDATE 9/1)

●

Face/Tailwall Matchpoint

Damage identified by ICRC QA

Damage observed and recorded by West


Sheet pile found out of interlock, per ICRC QA observations

Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING

NTS



PLAN



LEGEND

75' → Sheet length
6 1 2 3 4 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)
8/3 - RV
ICRC QA
DATE PULLED (LAST UPDATE 9/1)

● Face/Tailwall Matchpoint


Damage identified by ICRC QA
 Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations
 Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING

NTS



PLAN



LEGEND

75' → Sheet length
6 1 2 3 4 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)
8/3 - RV
ICRC QA
DATE PULLED (LAST UPDATE 9/1)

● Face/Tailwall Matchpoint


Damage identified by ICRC QA
Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING

NTS



PLAN



LEGEND

75' → Sheet length
6 1 2 3 4 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)
8/3 - RV
ICRC QA
DATE PULLED (LAST UPDATE 9/1)

● Face/Tailwall Matchpoint


Damage identified by ICRC QA
Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING

NTS



PLAN



LEGEND

75' → Sheet length
6 1 2 3 4 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)
8/3 - RV
ICRC QA
DATE PULLED (LAST UPDATE 9/1)

● Face/Tailwall Matchpoint


Damage identified by ICRC QA
Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

WBB 36
EXISTING

NTS




WBB 36
PLAN




WBB 37
EXISTING

NTS



WBB 37
PLAN



LEGEND

75'

100'

100'

100'

Sheet length

Sheet # in series

Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA

DATE PULLED (LAST UPDATE 9/1)

●

Face/Tailwall Matchpoint

Damage identified by ICRC QA


Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations


Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPDATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

WBB 38
EXISTING



WBB 38
PLAN




- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

WBB 39
EXISTING

NTS

NO EXISTING

WBB 39
PLAN




NE 1
EXISTING



NO EXISTING

NE 1
PLAN



75'

61-03-4

61-03-10

8/3 - RV

Sheet length

Sheet # in series

Sheet ID (Alpha for face, numeric for Tailwall)

ICRC QA

DATE PULLED (LAST UPDATE 9/1)

●

Face/Tailwall Matchpoint

Damage identified by ICRC QA

Damage observed and recorded by West

▲


Sheet pile found out of interlock, per ICRC QA observations

Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.



NE 2
PLAN




NE 3
EXISTING



NO EXISTING

NE 3
PLAN




- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 4
EXISTING



NO EXISTING

NE 4
PLAN




- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 5
EXISTING



NO EXISTING

NE 5
PLAN




- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.



NO EXISTING

NE 6
PLAN




- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 7
EXISTING



NO EXISTING

NE 7
PLAN



LEGEND

75'

1 2 3 4

5 6 7 8 9 10

Sheet length

Sheet # in series

Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA

DATE PULLED (LAST UPDATE 9/1)

●

Face/Tailwall Matchpoint

Damage identified by ICRC QA

Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations

Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 8
EXISTING



NO EXISTING

NE 8
PLAN



75'

1-23

8/3 - RV

Sheet length

Sheet # in series

Sheet ID (Alpha for face, numeric for Tailwall)

●

Face/Tailwall Matchpoint

Damage identified by ICRC QA

Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations

Dive inspection findings

ICRC QA


DATE PULLED (LAST UPDATE 9/1)

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.


NE 9
EXISTING

NTS


LEAVE PER SCOPE



NE 9
PLAN



LEGEND




● Face/Tailwall Matchpoint

Damage identified by ICRC QA
Damage observed and recorded by West


Sheet pile found out of interlock, per ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

**NE 10
EXISTING**




NE 10
PLAN




- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 11
EXISTING

NTS



NE 11
PLAN



LEGEND

75'

1, 2, 3

9, 10, 11

8/3 - RV

Sheet length

Sheet # in series

Sheet ID (Alpha for face, numeric for Tailwall)

ICRC QA

DATE PULLED (LAST UPDATE 9/1)

●

Face/Tailwall Matchpoint

Damage identified by ICRC QA

Damage observed and recorded by West


Sheet pile found out of interlock, per ICRC QA observations

Dive inspection findings


• ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
• UPATED 10/12/10
• * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
• West data from West cell by cell drawings, courtesy of West.
• ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 12
EXISTING

NTS



NE 12
PLAN



LEGEND

75'

1 2 3 4

9 10 11 12

Sheet length

Sheet # in series

Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA

DATE PULLED (LAST UPDATE 9/1)

● Face/Tailwall Matchpoint

Damage identified by ICRC QA

Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations


Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.


NE 31

EXISTING

NTS



PLAN




• ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
• UPATED 10/12/10
• * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
• West data from West cell by cell drawings, courtesy of West.
• ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.


NE 32
EXISTING



LEAVE PER SCOPE



NE 32
PLAN



LEGEND

75' Sheet length
1-100 Sheet # in series
97000000 Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED (LAST UPDATE 9/1)

Face/Tailwall Matchpoint

Damage identified by ICRC QA
Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 33
EXISTING



NO EXISTING

NE 33
PLAN




NE 34
EXISTING



NO EXISTING

NE 34
PLAN




NE 35
EXISTING



NO EXISTING

NE 35
PLAN




NE 36
EXISTING




NO EXISTING


NE 36
PLAN



NE 37
EXISTING (NTS)



NE 37
PLAN



LEGEND

75' → Sheet length
6' → Sheet # in series
970010 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)


● Face/Tailwall
Matchpoint

Damage identified by
ICRC QA
Damage observed and
recorded by West


Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 38
EXISTING (NTS)



NE 38
PLAN



LEGEND

75' → Sheet length
6' → Sheet # in series
97000000 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)


● Face/Tailwall
Matchpoint

Damage identified by
ICRC QA
Damage observed and
recorded by West


Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 39
EXISTING (NTS)



NE 39
PLAN



LEGEND

75' → Sheet length
6' → Sheet # in series
9700010 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall
Matchpoint


Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 40

EXISTING **NTS**




PLAN




- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 41

EXISTING
NTS



PLAN



LEGEND

75' → Sheet length
6' → Sheet # in series
9700910 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall
Matchpoint


Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 42


EXISTING 



PLAN



LEGEND



● Face/Tailwall
Matchpoint

Damage identified by ICRC QA


Damage observed and recorded by West

- Sheet pile found out of interlock, per ICRC QA observations
- Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 43

EXISTING
NTS



PLAN



LEGEND

75' → Sheet length
6 1 2 3 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall
Matchpoint


Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 44

EXISTING
NTS



PLAN



LEGEND

75' Sheet length
6' Sheet # in series
67890 Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

Face/Tailwall
Matchpoint



Damage identified by
ICRC QA



Damage observed and
recorded by West



Sheet pile found out
of interlock, per
ICRC QA observations




Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 45

EXISTING
NTS



PLAN



LEGEND

75' Sheet length
1-100 Sheet # in series
9788910 Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

Face/Tailwall
Matchpoint



Damage identified by
ICRC QA



Damage observed and
recorded by West



Sheet pile found out
of interlock, per
ICRC QA observations




Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 46

EXISTING
NTS



PLAN



LEGEND

75' → Sheet length
6 1 2 3 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall Matchpoint


Damage identified by ICRC QA
Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.


NE 47

EXISTING
NTS



FROM WINTER CLOSURE PLAN: "PULL AND INSPECT TAILWALLS FROM END ANCHOR TO INTERMEDIATE ANCHOR..."

PLAN



LEGEND

75' → Sheet length
6 1 2 3 → Sheet # in series
6 7 8 9 10 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall
Matchpoint


Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 48


EXISTING
NTS



PLAN



LEGEND



Face/Tailwall Matchpoint


Damage identified by ICRC QA
Damage observed and recorded by West

Sheet pile found out of interlock, per ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 49

EXISTING
NTS



PLAN



LEGEND

75'

60'

45'

30'

Sheet length

1

2

3

4

5

6

7

8

9

Sheet # in series

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

298

299

300

301

302

303

304

305

306

307

308

309

310

311

312

313

314

315

316

317

318

319

320

321

322

323

324

325

326

327

328

329

330

331

332

333

334

335

336

337

338

339

340

341

342

343

344

345

346

347

348

349

350

351

352

353

354

355

356

357

358

359

360

361

362

363

364

365

366

367

368

369

370

371

372

373

374

375

376

377

378

379

380

381

382

383

384

385

386

387

388

389

390

391

392

393

394

395

396

397

398

399

400

401

402

403

404

405

406

407

408

409

410

411

412

413

414

415

416

417

418

419

420

421

422

423

424

425

426

427

428

429

430

431

432

433

434

435

436

437

438

439

440

441

442

443

444

445

446

447

448

449

450

451

452

453

454

455

456

457

458

459

460

461

462

463

464

465

466

467

468

469

470

471

472

473

474

475

476

477

478

479

480

481

482

483

484

485

486

487

488

489

490

491

492

493

494

495

496

497

498

499

500

501

502

503

504

505

506

507

508

509

510

511

512

513

514

515

516

517

518

519

520

521

522

523

524

525

526

527

528

529

530

531

532

533

534

535

536

537

538

539

540

541

542

543

544

545

546

547

548

549

550

551

552

553

554

555

556

557

558

559

560

561

562

563

564

565

566

567

568

569

570

571

572

573

574

575

576

577

578

579

580

581

582

583

584

585

586

587

588

589

590

591

592

593

594

595

596

597

598

599

600

601

602

603

604

605

606

607

608

609

610

611

612

613

614

615

616

617

618

619

620

621

622

623

624

625

626

627

628

629

630

631

632

633

634

635

636

637

638

639

640

641

642

643

644

645

646

647

648

649

650

651

652

653

654

655

656

657

658

659

660

661

662

663

664

665

666

667

668

669

670

671

672

673

674

675

676

677

678

679

680

681

682

683

684

685

686

687

688

689

690

691

692

693

694

695

696

697

698

699

700

701

702

703

704

705

706

707

708

709

710

711

712

713

714

715

716

717

718

719

720

721

722

723

724

725

726

727

728

729

730

731

732

733

734

735

736

737

738

739

740

741

742

743

744

745

746

747

748

749

750

751

752

753

754

755

756

757

758

759

760

761

762

763

764

765

766

767

768

769

770

771

772

773

774

775

776

777

778

779

780

781

782

783

784

785

786

787

788

789

790

791

792

793

794

795

796

797

798

799

800

801

802

803

804

805

806

807

808

809

810

811

812

813

814

815

816

817

818

819

820

821

822

823

824

825

826

827

828

829

830

831

832

833

834

835

836

837

838

839

840

841

842

843

844

845

846

847

848

849

850

851

852

853

854

855

856

857

858

859

860

861

862

863

864

865

866

867

868

869

870

871

872

873

874

875

876

877

878

879

880

881

882

883

884

885

886

887

888

889

890

891

892

893

894

895

896

897

898

899

900

901

902

903

904

905

906

907

908

909

910

911

912

913

914

915

916

917

918

919

920

921

922

923

924

925

926

927

928

929

930

931

932

933

934

935

936

937

938

939

940

941

942

943

944

945

946

947

948

949

950

951

952

953

954

955

956

957

958

959

960

961

962

963

964

965

966

967

968

969

970

971

972

973

974

975

976

977

978

979

980

981

982

983

984

985

986

987

988

989

990

991

992

993

994

995

996

997

998

999

1000

1001

1002

1003

1004

1005

1006

1007

1008

1009

1010

1011

1012

1013

1014

1015

1016

1017

1018

1019

1020

1021

1022

1023

1024

1025

1026

1027

1028

1029

1030

1031

1032

1033

1034

1035

1036

1037

1038

1039

1040

1041

1042

1043

1044

1045

1046

1047

1048

1049

1050

1051

1052

1053

1054

1055

1056

1057

1058

1059

1060

1061

1062

1063

1064

1065

1066

1067

1068

1069

1070

1071

1072

1073

1074

1075

1076

1077

1078

1079

1080

1081

1082

1083

1084

1085

1086

1087

1088

1089

1090

1091

1092

1093

1094

1095

1096

1097

1098

1099

1100

1101

1102

1103

1104

1105

1106

1107

1108

1109

1110

1111

1112

1113

1114

1115

1116

1117

1118

1119

1120

1121

1122

1123

1124

1125

1126

1127

1128

1129

1130

1131

1132

1133

1134

1135

1136

1137

1138

1139

1140

1141

1142

1143

1144

1145

1146

1147

1148

1149

1150

1151

1152

1153

1154

1155

1156

1157

1158

1159

1160

1161

1162

1163

1164

1165

1166

1167

1168

1169

1170

1171

1172

1173

1174

1175

1176

1177

1178

1179

1180

1181

1182

1183

1184

1185

1186

1187

1188

1189

1190

1191

1192

1193

1194

1195

1196

1197

1198

1199

1200

1201

1202

1203

1204

1205

1206

1207

1208

1209

1210

1211

1212

1213

1214

1215

1216

1217

1218

1219

1220

1221

1222

1223

1224

1225

1226

1227

1228

1229

1230

1231

1232

1233

1234

1235

1236

1237

1238

1239

1240

1241

1242

1243

1244

1245

1246

1247

1248

1249

1250

1251

1252

1253

1254

1255

1256

1257

1258

1259

1260

1261

1262

1263

1264

1265

1266

1267

1268

1269

1270

1271

1272

1273

1274

1275

1276

1277

1278

1279

1280

1281

1282

1283

1284

1285

1286

1287

1288

1289

1290

1291

1292

1293

1294

1295

1296

1297

1298

1299

1300

1301

1302

1303

1304

1305

1306

1307

1308

1309

1310

1311

1312

1313

1314

1315

1316

1317

1318

1319

1320

1321

1322

1323

1324

1325

1326

1327

1328

1329

1330

1331

1332

1333

1334

1335

1336

1337

1338

1339

1340

1341

1342

1343

1344

1345

1346

1347

1348

1349

1350

1351

1352

1353

1354

1355

1356

1357

1358

1359

1360

1361

1362

1363

1364

1365

1366

1367

1368

1369

1370

1371

1372

1373

1374

1375

1376

1377

1378

1379

1380

1381

1382

1383

1384

1385

1386

1387

1388

1389

1390

1391

1392

1393

1394

1395

1396

1397

1398

1399

1400

1401

1402

1403

1404

1405

1406

1407

1408

1409

1410

1411

1412

1413

1414

1415

1416

1417

1418

1419

1420

1421

1422

1423

1424

1425

1426

1427

1428

1429

1430

1431

1432

1433

1434

1435

1436

1437

1438

1439

1440

1441

1442


1443

1444

1445


NE 50

EXISTING
NTS



FROM WINTER CLOSURE PLAN: "PULL AND INSPECT TAILWALLS FROM END ANCHOR TO INTERMEDIATE ANCHOR..."

PLAN



LEGEND

75' ← Sheet length
6' ← Sheet # in series
9700010 ← Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall
Matchpoint

Damage identified by
ICRC QA
Damage observed and
recorded by West


Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 51


EXISTING

NTS



FROM WINTER CLOSURE PLAN: "PULL AND INSPECT TAILWALLS FROM END ANCHOR TO INTERMEDIATE ANCHOR..."

PLAN



LEGEND

75' Sheet length
1-2-3 Sheet # in series
97-88-10 Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

Face/Tailwall
Matchpoint


Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 52

EXISTING **NTS**



PLAN



LEGEND

Diagram illustrating the components of a sheet label:

- 75' ← Sheet length
- Sheet # in series
- Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE

● Face/Tailwall Matchpoint

Damage identified by ICRC QA


Damage observed and recorded by Vest

- Sheet pile found out of interlock, per ICRC QA observations
- Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 53


EXISTING
NTS



PLAN



LEGEND



ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

Face/Tailwall
Matchpoint


Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 54

EXISTING
NTS



PLAN



LEGEND

75' → Sheet length
6' → Sheet # in series
6788910 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall
Matchpoint



Damage identified by
ICRC QA



Damage observed and
recorded by West



Sheet pile found out
of interlock, per
ICRC QA observations




Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 55

EXISTING
NTS



PLAN



LEGEND

75' Sheet length
1-100 Sheet # in series
100-100 Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA

DATE PULLED
(LAST UPDATE 9/1)

Face/Tailwall
Matchpoint



Damage identified by
ICRC QA



Damage observed and
recorded by West



Sheet pile found out
of interlock, per
ICRC QA observations




Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.


NE 56

EXISTING
NTS



FROM WINTER CLOSURE PLAN: "PULL AND INSPECT TAILWALLS FROM END ANCHOR TO INTERMEDIATE ANCHOR..."

PLAN



LEGEND

75' → Sheet length
61.0m → Sheet # in series
61.0m → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall
Matchpoint

Damage identified by
ICRC QA
Damage observed and
recorded by West


Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.


NE 57

EXISTING

NTS



PLAN



LEGEND

Sheet length
Sheet # in series
Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

Face/Tailwall
Matchpoint


Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 58

EXISTING 



PLAN



LEGEND

Diagram illustrating the layout of a sheet (Sheet # 4) with labels:

- Sheet length (75')
- Sheet # in series (4)
- Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RW

ICRC QA
DATE Pulled
(LAST UPDATE

● Face/Tailwall Matchpoint

Damage identified by ICRC QA


Damage observed and recorded by West

	Sheet pile found out of interlock, per ICRC QA observations
	Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 59


EXISTING
NTS



PLAN



LEGEND



DATE PULLED
(LAST UPDATE 9/1)

Face/Tailwall
Matchpoint

Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING 



The diagram illustrates the layout of a sheet pile wall. The top section shows the alignment of the wall with pile numbers 1 through 112. The wall is divided into sections with varying lengths: 90' for the first 6 piles, 80' for the next 3 piles, 75' for the next 3 piles, and then a series of 10' sections for the remaining piles. A 'WYE' is indicated at the 90' mark. The bottom section shows the 'TAILWALL ON RIGHT' and the 'FACE/TAILWALL MATCHPOINT'.

LEGEND

- Sheet length: 75'
- Sheet # in series: 1, 2, 3, 4
- Sheet ID (Alpha for face, numeric for Tailwall): 8, 9, 10
- Face/Tailwall Matchpoint: ●
- Damage identified by ICRC QA: [Blue hatched box]
- Damage observed and recorded by Vest®: [Green hatched box]
- Sheet pile found out of interlock, per ICRC QA observations: [Blue triangle]
- Dive inspection findings: [Red grid box]

8/3 - RV

Diagram illustrating the components of a sheet label:

- 75' ← Sheet length
- Sheet # in series
- Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RW

ICRC QA
DATE Pulled
(Last Update 9/1)

● Face/Tailwall Matchpoint

 Damage identified by ICRC QA

Damage observed and recorded by West®


Sheet pile found out of interlock, per ICRC QA observations

Dive inspection findings


- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

NE 61

EXISTING
NTS



PLAN



LEGEND

75' → Sheet length
6' → Sheet # in series
6788910 → Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

● Face/Tailwall
Matchpoint

Damage identified by
ICRC QA
Damage observed and
recorded by West

Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

EXISTING **NTS**



ICRC QA
DATE Pulled
(LAST UPDATE

Damage identified by ICRC QA


Damage observed and recorded by West

- Sheet pile found out of interlock, per ICRC QA observations
- Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.


NE 63

EXISTING
NTS



FROM WINTER CLOSURE PLAN: "PULL AND INSPECT TAILWALLS FROM END ANCHOR TO INTERMEDIATE ANCHOR..."

PLAN




LEGEND

75' → Sheet length
6 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 1040 1041 1042 1043 1044 1045 1046 1047 1048 1049 1050 1051 1052 1053 1054 1055 1056 1057 1058 1059 1060 1061 1062 1063 1064 1065 1066 1067 1068 1069 1070 1071 1072 1073 1074 1075 1076 1077 1078 1079 1080 1081 1082 1083 1084 1085 1086 1087 1088 1089 1090 1091 1092 1093 1094 1095 1096 1097 1098 1099 1100 1101 1102 1103 1104 1105 1106 1107 1108 1109 1110 1111 1112 1113 1114 1115 1116 1117 1118 1119 1120 1121 1122 1123 1124 1125 1126 1127 1128 1129 1130 1131 1132 1133 1134 1135 1136 1137 1138 1139 1140 1141 1142 1143 1144 1145 1146 1147 1148 1149 1150 1151 1152 1153 1154 1155 1156 1157 1158 1159 1160 1161 1162 1163 1164 1165 1166 1167 1168 1169 1170 1171 1172 1173 1174 1175 1176 1177 1178 1179 1180 1181 1182 1183 1184 1185 1186 1187 1188 1189 1190 1191 1192 1193 1194 1195 1196 1197 1198 1199 1200 1201 1202 1203 1204 1205 1206 1207 1208 1209 1210 1211 1212 1213 1214 1215 1216 1217 1218 1219 1220 1221 1222 1223 1224 1225 1226 1227 1228 1229 1230 1231 1232 1233 1234 1235 1236 1237 1238 1239 1240 1241 1242 1243 1244 1245 1246 1247 1248 1249 1250 1251 1252 1253 1254 1255 1256 1257 1258 1259 1260 1261 1262 1263 1264 1265 1266 1267 1268 1269 1270 1271 1272 1273 1274 1275 1276 1277 1278 1279 1280 1281 1282 1283 1284 1285 1286 1287 1288 1289 1290 1291 1292 1293 1294 1295 1296 1297 1298 1299 1300 1301 1302 1303 1304 1305 1306 1307 1308 1309 1310 1311 1312 1313 1314 1315 1316 1317 1318 1319 1320 1321 1322 1323 1324 1325 1326 1327 1328 1329 1330 1331 1332 1333 1334 1335 1336 1337 1338 1339 1340 1341 1342 1343 1344 1345 1346 1347 1348 1349 1350 1351 1352 1353 1354 1355 1356 1357 1358 1359 1360 1361 1362 1363 1364 1365 1366 1367 1368 1369 1370 1371 1372 1373 1374 1375 1376 1377 1378 1379 1380 1381 1382 1383 1384 1385 1386 1387 1388 1389 1390 1391 1392 1393 1394 1395 1396 1397 1398 1399 1400 1401 1402 1403 1404 1405 1406 1407 1408 1409 1410 1411 1412 1413 1414 1415 1416 1417 1418 1419 1420 1421 1422 1423 1424 1425 1426 1427 1428 1429 1430 1431 1432 1433 1434 1435 1436 1437 1438 1439 1440 1441 1442 1443 1444 1445 1446 1447 1448 1449 1450 1451 1452 1453 1454 1455 1456 1457 1458 1459 1460 1461 1462 1463 1464 1465 1466 1467 1468 1469 1470 1471 1472 1473 1474 1475 1476 1477 1478 1479 1480 1481 1482 1483 1484 1485 1486 1487 1488 1489 1490 1491 1492 1493 1494 1495 1496 1497 1498 1499 1500 1501 1502 1503 1504 1505 1506 1507 1508 1509 1510 1511 1512 1513 1514 1515 1516 1517 1518 1519 1520 1521 1522 1523 1524 1525 1526 1527 1528 1529 1530 1531 1532 1533 1534 1535 1536 1537 1538 1539 1540 1541 1542 1543 1544 1545 1546 1547 1548 1549 1550 1551 1552 1553 1554 1555 1556 1557 1558 1559 1560 1561 1562 1563 1564 1565 1566 1567 1568 1569 1570 1571 1572 1573 1574 1575 1576 1577 1578 1579 1580 1581 1582 1583 1584 1585 1586 1587 1588 1589 1590 1591 1592 1593 1594 1595 1596 1597 1598 1599 1600 1601 1602 1603 1604 1605 1606 1607 1608 1609 1610 1611 1612 1613 1614 1615 1616 1617 1618 1619 1620 1621 1622 1623 1624 1625 1626 1627 1628 1629 1630 1631 1632 1633 1634 1635 1636 1637 1638 1639 1640 1641 1642 1643 1644 1645 1646 1647 1648 1649 1650 1651 1652 1653 1654 1655 1656 1657 1658 1659 1660 1661 1662 1663 1664 1665 1666 1667 1668 1669 1670 1671 1672 1673 1674 1675 1676 1677 1678 1679 1680 1681 1682 1683 1684 1685 1686 1687 1688 1689 1690 1691 1692 1693 1694 1695 1696 1697 1698 1699 1700 1701 1702 1703 1704 1705 1706 1707 1708 1709 1710 1711 1712 1713 1714 1715 1716 1717 1718 1719 1720 1721 1722 1723 1724 1725 1726 1727 1728 1729 1730 1731 1732 1733 1734 1735 1736 1737 1738 1739 1740 1741 1742 1743 1744 1745 1746 1747 1748 1749 1750 1751 1752 1753 1754 1755 1756 1757 1758 1759 1760 1761 1762 1763 1764 1765 1766 1767 1768 1769 1770 1771 1772 1773 1774 1775 1776 1777 1778 1779 1780 1781 1782 1783 1784 1785 1786 1787 1788 1789 1790 1791 1792 1793 1794 1795 1796 1797 1798 1799 1800 1801 1802 1803 1804 1805 1806 1807 1808 1809 1810 1811 1812 1813 1814 1815 1816 1817 1818 1819 1820 1821 1822 1823 1824 1825 1826 1827 1828 1829 1830 1831 1832 1833 1834 1835 1836 1837 1838 1839 1840 1841 1842 1843 1844 1845 1846 1847 1848 1849 1850 1851 1852 1853 1854 1855 1856 1857 1858 1859 1860 1861 1862 1863 1864 1865 1866 1867 1868 1869 1870 1871 1872 1873 1874 1875 1876 1877 1878 1879 1880 1881 1882 1883 1884 1885 1886 1887 1888 1889 1890 1891 1892 1893 1894 1895 1896 1897 1898 1899 1900 1901 1902 1903 1904 1905 1906 1907 1908 1909 1910 1911 1912 1913 1914 1915 1916 1917 1918 1919 1920 1921 1922 1923 1924 1925 1926 1927 1928 1929 1930 1931 1932 1933 1934 1935 1936 1937 1938 1939 1940 1941 1942 1943 1944 1945 1946 1947 1948 1949 1950 1951 1952 1953 1954 1955 1956 1957 1958 1959 1960 1961 1962 1963 1964 1965 1966 1967 1968 1969 1970 1971 1972 1973 1974 1975 1976 1977 1978 1979 1980 1981 1982 1983 1984 1985 1986 1987 1988 1989 1990 1991 1992 1993 1994 1995 1996 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006 2007 2008 2009 2010 2011 2012 2013 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050 2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062 2063 2064 2065 2066 2067 2068 2069 2070 2071 2072 2073 2074 2075 2076 2077 2078 2079 2080 2081 2082 2083 2084 2085 2086 2087 2088 2089 2090 2091 2092 2093 2094 2095 2096 2097 2098 2099 2100 2101 2102 2103 2104 2105 2106 2107 2108 2109 2110 2111 2112 2113 2114 2115 2116 2117 2118 2119 2120 2121 2122 2123 2124 2125 2126 2127 2128 2129 2130 2131 2132 2133 2134 2135 2136 2137 2138 2139 2140 2141 2142 2143 2144 2145 2146 2147 2148 2149 2150 2151 2152 2153 2154 2155 2156 2157 2158 2159 2160 2161 2162 2163 2164 2165 2166 2167 2168 2169 2170 2171 2172 2173 2174 2175 2176 2177 2178 2179 2180 2181 2182 2183 2184 2185 2186 2187 2188 2189 2190 2191 2192 2193 2194 2195 2196 2197 2198 2199 2200 2201 2202 2203 2204 2205 2206 2207 2208 2209 2210 2211 2212 2213 2214 2215 2216 2217 2218 2219 2220 2221 2222 2223 2224 2225 2226 2227 2228 2229 2230 2231 2232 2233 2234 2235 2236 2237 2238 2239 2240 2241 2242 2243 2244 2245 2246 2247 2248 2249 2250 2251 2252 2253 2254 2255 2256 2257 2258 2259 2260 2261 2262 2263 2264 2265 2266 2267 2268 2269 2270 2271 2272 2273 2274 2275 2276 2277 2278 2279 2280 2281 2282 2283 2284 2285 2286 2287 2288 2289 2290 2291 2292 2293 2294 2295 2296 2297 2298 2299 2300 2301 2302 2303 2304 2305 2306 2307 2308 2309 2310 2311 2312 2313 2314 2315 2316 2317 2318 2319 2320 2321 2322 2323 2324 2325 2326 2327 2328 2329 2330 2331 2332 2333 2334 2335 2336 2337 2338 2339 2340 2341 2342 2343 2344 2345 2346 2347 2348 2349 2350 2351 2352 2353 2354 2355 2356 2357 2358 2359 2360 2361 2362 2363 2364 2365 2366 2367 2368 2369 2370 2371 2372 2373 2374 2375 2376 2377 2378 2379 2380 2381 2382 2383 2384 2385 2386 2387 2388 2389 2390 2391 2392 2393 2394 2395 2396 2397 2398 2399 2400 2401 2402 2403 2404 2405 2406 2407 2408 2409 2410 2411 2412 2413 2414 2415 2416 2417 2418 2419 2420 2421 2422 2423 2424 2425 2426 2427 2428 2429 2430 2431 2432 2433 2434 2435 2436 2437 2438 2439 2440 2441 2442 2443 2444 2445 2446 2447 2448 2449 2450 2451 2452 2453 2454 2455 2456 2457 2458 2459 2460 2461 2462 2463 2464 2465 2466 2467 2468 2469 2470 2471 2472 2473 2474 2475 2476 2477 2478 2479 2480 2481 2482 2483 2484 2485 2486 2487 2488 2489 2490 2491 2492 2493 2494 2495 2496 2497 2498 2499 2500 2501 2502 2503 2504 2505 2506 2507 2508 2509 2510 2511 2512 2513 2514 2515 2516 2517 2518 2519 2520 2521 2522 2523 2524 2525 2526 2527 2528 2529 2530 2531 2532 2533 2534 2535 2536 2537 2538 2539 2540 2541 2542 2543 2544 2545 2546 2547 2548 2549 2550 2551 2552 2553 2554 2555 2556 2557 2558 2559 2560 2561 2562 2563 2564 2565 2566 2567 2568 2569 2570 2571 2572 2573 2574 2575 2576 257


NE 64

EXISTING
NTS



FROM WINTER CLOSURE PLAN: "PULL AND INSPECT TAILWALLS FROM END ANCHOR TO INTERMEDIATE ANCHOR..."

PLAN




LEGEND

75' → Sheet length
6 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 1040 1041 1042 1043 1044 1045 1046 1047 1048 1049 1050 1051 1052 1053 1054 1055 1056 1057 1058 1059 1060 1061 1062 1063 1064 1065 1066 1067 1068 1069 1070 1071 1072 1073 1074 1075 1076 1077 1078 1079 1080 1081 1082 1083 1084 1085 1086 1087 1088 1089 1090 1091 1092 1093 1094 1095 1096 1097 1098 1099 1100 1101 1102 1103 1104 1105 1106 1107 1108 1109 1110 1111 1112 1113 1114 1115 1116 1117 1118 1119 1120 1121 1122 1123 1124 1125 1126 1127 1128 1129 1130 1131 1132 1133 1134 1135 1136 1137 1138 1139 1140 1141 1142 1143 1144 1145 1146 1147 1148 1149 1150 1151 1152 1153 1154 1155 1156 1157 1158 1159 1160 1161 1162 1163 1164 1165 1166 1167 1168 1169 1170 1171 1172 1173 1174 1175 1176 1177 1178 1179 1180 1181 1182 1183 1184 1185 1186 1187 1188 1189 1190 1191 1192 1193 1194 1195 1196 1197 1198 1199 1200 1201 1202 1203 1204 1205 1206 1207 1208 1209 1210 1211 1212 1213 1214 1215 1216 1217 1218 1219 1220 1221 1222 1223 1224 1225 1226 1227 1228 1229 1230 1231 1232 1233 1234 1235 1236 1237 1238 1239 1240 1241 1242 1243 1244 1245 1246 1247 1248 1249 1250 1251 1252 1253 1254 1255 1256 1257 1258 1259 1260 1261 1262 1263 1264 1265 1266 1267 1268 1269 1270 1271 1272 1273 1274 1275 1276 1277 1278 1279 1280 1281 1282 1283 1284 1285 1286 1287 1288 1289 1290 1291 1292 1293 1294 1295 1296 1297 1298 1299 1300 1301 1302 1303 1304 1305 1306 1307 1308 1309 1310 1311 1312 1313 1314 1315 1316 1317 1318 1319 1320 1321 1322 1323 1324 1325 1326 1327 1328 1329 1330 1331 1332 1333 1334 1335 1336 1337 1338 1339 1340 1341 1342 1343 1344 1345 1346 1347 1348 1349 1350 1351 1352 1353 1354 1355 1356 1357 1358 1359 1360 1361 1362 1363 1364 1365 1366 1367 1368 1369 1370 1371 1372 1373 1374 1375 1376 1377 1378 1379 1380 1381 1382 1383 1384 1385 1386 1387 1388 1389 1390 1391 1392 1393 1394 1395 1396 1397 1398 1399 1400 1401 1402 1403 1404 1405 1406 1407 1408 1409 1410 1411 1412 1413 1414 1415 1416 1417 1418 1419 1420 1421 1422 1423 1424 1425 1426 1427 1428 1429 1430 1431 1432 1433 1434 1435 1436 1437 1438 1439 1440 1441 1442 1443 1444 1445 1446 1447 1448 1449 1450 1451 1452 1453 1454 1455 1456 1457 1458 1459 1460 1461 1462 1463 1464 1465 1466 1467 1468 1469 1470 1471 1472 1473 1474 1475 1476 1477 1478 1479 1480 1481 1482 1483 1484 1485 1486 1487 1488 1489 1490 1491 1492 1493 1494 1495 1496 1497 1498 1499 1500 1501 1502 1503 1504 1505 1506 1507 1508 1509 1510 1511 1512 1513 1514 1515 1516 1517 1518 1519 1520 1521 1522 1523 1524 1525 1526 1527 1528 1529 1530 1531 1532 1533 1534 1535 1536 1537 1538 1539 1540 1541 1542 1543 1544 1545 1546 1547 1548 1549 1550 1551 1552 1553 1554 1555 1556 1557 1558 1559 1560 1561 1562 1563 1564 1565 1566 1567 1568 1569 1570 1571 1572 1573 1574 1575 1576 1577 1578 1579 1580 1581 1582 1583 1584 1585 1586 1587 1588 1589 1590 1591 1592 1593 1594 1595 1596 1597 1598 1599 1600 1601 1602 1603 1604 1605 1606 1607 1608 1609 1610 1611 1612 1613 1614 1615 1616 1617 1618 1619 1620 1621 1622 1623 1624 1625 1626 1627 1628 1629 1630 1631 1632 1633 1634 1635 1636 1637 1638 1639 1640 1641 1642 1643 1644 1645 1646 1647 1648 1649 1650 1651 1652 1653 1654 1655 1656 1657 1658 1659 1660 1661 1662 1663 1664 1665 1666 1667 1668 1669 1670 1671 1672 1673 1674 1675 1676 1677 1678 1679 1680 1681 1682 1683 1684 1685 1686 1687 1688 1689 1690 1691 1692 1693 1694 1695 1696 1697 1698 1699 1700 1701 1702 1703 1704 1705 1706 1707 1708 1709 1710 1711 1712 1713 1714 1715 1716 1717 1718 1719 1720 1721 1722 1723 1724 1725 1726 1727 1728 1729 1730 1731 1732 1733 1734 1735 1736 1737 1738 1739 1740 1741 1742 1743 1744 1745 1746 1747 1748 1749 1750 1751 1752 1753 1754 1755 1756 1757 1758 1759 1760 1761 1762 1763 1764 1765 1766 1767 1768 1769 1770 1771 1772 1773 1774 1775 1776 1777 1778 1779 1780 1781 1782 1783 1784 1785 1786 1787 1788 1789 1790 1791 1792 1793 1794 1795 1796 1797 1798 1799 1800 1801 1802 1803 1804 1805 1806 1807 1808 1809 1810 1811 1812 1813 1814 1815 1816 1817 1818 1819 1820 1821 1822 1823 1824 1825 1826 1827 1828 1829 1830 1831 1832 1833 1834 1835 1836 1837 1838 1839 1840 1841 1842 1843 1844 1845 1846 1847 1848 1849 1850 1851 1852 1853 1854 1855 1856 1857 1858 1859 1860 1861 1862 1863 1864 1865 1866 1867 1868 1869 1870 1871 1872 1873 1874 1875 1876 1877 1878 1879 1880 1881 1882 1883 1884 1885 1886 1887 1888 1889 1890 1891 1892 1893 1894 1895 1896 1897 1898 1899 1900 1901 1902 1903 1904 1905 1906 1907 1908 1909 1910 1911 1912 1913 1914 1915 1916 1917 1918 1919 1920 1921 1922 1923 1924 1925 1926 1927 1928 1929 1930 1931 1932 1933 1934 1935 1936 1937 1938 1939 1940 1941 1942 1943 1944 1945 1946 1947 1948 1949 1950 1951 1952 1953 1954 1955 1956 1957 1958 1959 1960 1961 1962 1963 1964 1965 1966 1967 1968 1969 1970 1971 1972 1973 1974 1975 1976 1977 1978 1979 1980 1981 1982 1983 1984 1985 1986 1987 1988 1989 1990 1991 1992 1993 1994 1995 1996 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006 2007 2008 2009 2010 2011 2012 2013 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050 2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062 2063 2064 2065 2066 2067 2068 2069 2070 2071 2072 2073 2074 2075 2076 2077 2078 2079 2080 2081 2082 2083 2084 2085 2086 2087 2088 2089 2090 2091 2092 2093 2094 2095 2096 2097 2098 2099 2100 2101 2102 2103 2104 2105 2106 2107 2108 2109 2110 2111 2112 2113 2114 2115 2116 2117 2118 2119 2120 2121 2122 2123 2124 2125 2126 2127 2128 2129 2130 2131 2132 2133 2134 2135 2136 2137 2138 2139 2140 2141 2142 2143 2144 2145 2146 2147 2148 2149 2150 2151 2152 2153 2154 2155 2156 2157 2158 2159 2160 2161 2162 2163 2164 2165 2166 2167 2168 2169 2170 2171 2172 2173 2174 2175 2176 2177 2178 2179 2180 2181 2182 2183 2184 2185 2186 2187 2188 2189 2190 2191 2192 2193 2194 2195 2196 2197 2198 2199 2200 2201 2202 2203 2204 2205 2206 2207 2208 2209 2210 2211 2212 2213 2214 2215 2216 2217 2218 2219 2220 2221 2222 2223 2224 2225 2226 2227 2228 2229 2230 2231 2232 2233 2234 2235 2236 2237 2238 2239 2240 2241 2242 2243 2244 2245 2246 2247 2248 2249 2250 2251 2252 2253 2254 2255 2256 2257 2258 2259 2260 2261 2262 2263 2264 2265 2266 2267 2268 2269 2270 2271 2272 2273 2274 2275 2276 2277 2278 2279 2280 2281 2282 2283 2284 2285 2286 2287 2288 2289 2290 2291 2292 2293 2294 2295 2296 2297 2298 2299 2300 2301 2302 2303 2304 2305 2306 2307 2308 2309 2310 2311 2312 2313 2314 2315 2316 2317 2318 2319 2320 2321 2322 2323 2324 2325 2326 2327 2328 2329 2330 2331 2332 2333 2334 2335 2336 2337 2338 2339 2340 2341 2342 2343 2344 2345 2346 2347 2348 2349 2350 2351 2352 2353 2354 2355 2356 2357 2358 2359 2360 2361 2362 2363 2364 2365 2366 2367 2368 2369 2370 2371 2372 2373 2374 2375 2376 2377 2378 2379 2380 2381 2382 2383 2384 2385 2386 2387 2388 2389 2390 2391 2392 2393 2394 2395 2396 2397 2398 2399 2400 2401 2402 2403 2404 2405 2406 2407 2408 2409 2410 2411 2412 2413 2414 2415 2416 2417 2418 2419 2420 2421 2422 2423 2424 2425 2426 2427 2428 2429 2430 2431 2432 2433 2434 2435 2436 2437 2438 2439 2440 2441 2442 2443 2444 2445 2446 2447 2448 2449 2450 2451 2452 2453 2454 2455 2456 2457 2458 2459 2460 2461 2462 2463 2464 2465 2466 2467 2468 2469 2470 2471 2472 2473 2474 2475 2476 2477 2478 2479 2480 2481 2482 2483 2484 2485 2486 2487 2488 2489 2490 2491 2492 2493 2494 2495 2496 2497 2498 2499 2500 2501 2502 2503 2504 2505 2506 2507 2508 2509 2510 2511 2512 2513 2514 2515 2516 2517 2518 2519 2520 2521 2522 2523 2524 2525 2526 2527 2528 2529 2530 2531 2532 2533 2534 2535 2536 2537 2538 2539 2540 2541 2542 2543 2544 2545 2546 2547 2548 2549 2550 2551 2552 2553 2554 2555 2556 2557 2558 2559 2560 2561 256


NE 65

EXISTING

NTS



PLAN



LEGEND

75' Sheet length
6' Sheet # in series
6' Sheet ID (Alpha for face, numeric for Tailwall)

8/3 - RV

ICRC QA
DATE PULLED
(LAST UPDATE 9/1)

Face/Tailwall
Matchpoint

Damage identified by
ICRC QA
Damage observed and
recorded by West


Sheet pile found out
of interlock, per
ICRC QA observations
Dive inspection findings

- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.


NE 65/66 (BK) TAILWALL

EXISTING


NTS




PLAN




NE 66
EXISTING





NE 66
PLAN?



LEGEND



● Face/Tailwall
Matchpoint




- ICRC INTERNAL DOCUMENT - DO NOT DISTRIBUTE
- UPATED 10/12/10
- * Data obtained courtesy of West Construction, final determination of damage to be made by ICRC based on multiphase QA inspections.
- West data from West cell by cell drawings, courtesy of West.
- ICRC observation data obtained from ICRC 'Drive/Pull Summary Log' updated 09/30/2010.

Article VIII. Exhibit C

Post Dredging Subsidence

Subsidence Photos



Cell 60



Cell 60



Cell 60



Cell 66



Cell 66



Cell 66

Subsidence Photos



Cell 63





Cell 53



Cell 27

Subsurface Rocks



Area of known occurrence of boulders



421 West First Avenue, Suite 200
Anchorage, Alaska 99501
(907) 561-4272
www.ICRCsolutions.com

Port of Anchorage Intermodal Expansion Project
Estimated Locations of Armor Rock Obstructions

Sheet 1 of 1

10-7-10

Boulders Photos



Cell 11

